

# Access Compliance Report

## Public Rights-of-Way

### (Island Curb Cuts)

Intersection ID: 8925	Main Street: E_W_T_HARRIS_BV	Cross Street: THE_PLAZA	Location: E
ADA ID: 92A721D872FA	Curb Cut Type: MedianRefuge2	Initial Pass/Fail: Pass	Overall Compliance: No
Codes/Mitigation Info/Possible Solution		Field Measurements/Component Compliance	
Severity Score: 10			



Possible Solutions:

**Fix Gutter Ponding. Remove & Replace Gutter.**

Surveyor Notes:

**N/A**

PROW/ADA:

**N/A**

Total Cost: \$ 1250.00

Compliance	Description	Data	Compliance	Description	Data
Yes	Refuge 1 Length (In)	42.5	No	Gutter 1 Ponding?	Yes
Yes	Refuge 1 Width (In)	72.0	Yes	Gutter 1 Lip Ht (In)	0.0
Yes	Refuge 1 Slope (%)	1.7	Yes	Gutter 1 Slope (%)	0.3
Yes	Refuge 1 X Slope (%)	0.8	Yes	Gutter 1 X Slope (%)	1.7
N/A	Painted X Walk1?	Yes	Yes	DWS 1 Provided?	Yes
N/A	X Walk 1 Direction	To S	Yes	DWS 1 Contrast?	Yes
N/A	X Walk 1 Width (In)	111.0	Yes	DWS 1 Length (In)	24.0
N/A	Road 1 Slope (%)	0.7	Yes	DWS 1 Full Width?	Yes
N/A	Road 1 X Slope (%)	2.2	Yes	DWS 1 Offset (In)	1.0
Yes	Refuge 2 Length (In)	42.5	No	Gutter 2 Ponding?	Yes
Yes	Refuge 2 Width (In)	72.0	Yes	Gutter 2 Lip Ht (In)	0.0
Yes	Refuge 2 Slope (%)	0.6	No	Gutter 2 Slope (%)	6.7
Yes	Refuge 2 X Slope (%)	1.3	Yes	Gutter 2 X Slope (%)	1.5
N/A	Painted X Walk2?	Yes	Yes	DWS 2 Provided?	Yes
N/A	X Walk 2 Direction	To N	Yes	DWS 2 Contrast?	Yes
N/A	X Walk 2 Width (In)	110.0	Yes	DWS 2 Length (In)	24.0
N/A	Road 2 Slope (%)	1.1	Yes	DWS 2 Full Width?	Yes
N/A	Road 2 X Slope (%)	0.7	Yes	DWS 2 Offset (In)	1.0
N/A	Refuge 3 Length (in)	N/A	N/A	Gutter 3 Ponding?	No
N/A	Refuge 3 Width (in)	N/A	N/A	Gutter 3 Lip Ht (in)	N/A
N/A	Refuge 3 Slope (%)	N/A	N/A	Gutter 3 Slope (%)	N/A
N/A	Refuge 3 XSlope (%)	N/A	N/A	Gutter 3 XSlope (%)	N/A
N/A	Painted X Walk3?	No	N/A	DWS 3 Provided?	N/A
N/A	X Walk 3 Direction	N/A	N/A	DWS 3 Contrast?	N/A
N/A	X Walk 3 Width (in)	N/A	N/A	DWS 3 Length (in)	N/A
N/A	Road 3 Slope (%)	N/A	N/A	DWS 3 Full Width?	N/A
N/A	Road 3 XSlope (%)	N/A	N/A	DWS 3 Offset (in)	N/A
Yes	Any Obstructions?	No	N/A	Storm Grate/Utility Hazard?	No
N/A	Obstruction Type		N/A	Storm Grate/Utility Type	
N/A	Surface Condition	Good	N/A		N/A

