

## Access Compliance Report Public Rights-of-Way (Island Curb Cuts)



Data

N/A

Intersection ID: 13201Main Street: REMOUNT\_RDCross Street: WATSON\_DRLocation:NADA ID: 95B027E57EE0Curb Cut Type: MedianRefuge2Initial Pass/Fail: FailOverall Compliance: NoSeverity Score: 1.25

Codes/Mitigation Info/Possible Solution

## Field Measurements/Component Compliance

Data Compliance Description

**54.0 N/A** Gutter 1 Ponding?

**96.0** N/A Gutter 1 Lip Ht (In)

**0.6 N/A** Gutter 1 Slope (%)

No N/A DWS 1 Provided?

N/A N/A DWS 1 Length (In)

3.6 N/A DWS 1 Full Width?

**3.7 N/A** DWS 1 Offset (In)

**53.0 N/A** Gutter 2 Ponding?

**96.0** N/A Gutter 2 Lip Ht (In)

**3.3 N/A** Gutter 2 Slope (%)

No N/A DWS 2 Provided?

N/A N/A DWS 2 Length (In)

2.5 N/A DWS 2 Full Width?

To E N/A DWS 2 Contrast?

4.2 N/A Gutter 2 X Slope (%)

To W N/A DWS 1 Contrast?

**4.5 N/A** Gutter 1 X Slope (%)



Remove & Replace Entire Refuge.

Surveyor Notes:

Possible Solutions:

N/A

PROW/ADA:

N/A

Com	pliance Description			
Yes	Refuge 1 Length (In)			
Yes	Refuge 1 Width (In)			
Yes	Refuge 1 Slope (%)			
Yes	Refuge 1 X Slope (%)			
N/A	Painted X Walk1?			
N/A	X Walk 1 Direction			
N/A	X Walk 1 Width (In)			
N/A	Road 1 Slope (%)			
N/A	Road 1 X Slope (%)			
Yes	Refuge 2 Length (In)			
Yes	Refuge 2 Width (In)			
Yes	Refuge 2 Slope (%)			
Yes	Refuge 2 X Slope (%)			
N/A	Painted X Walk2?			
N/A	X Walk 2 Direction			
N/A	X Walk 2 Width (In)			
N/A	Road 2 Slope (%)			
N/A	Road 2 X Slope (%)			
N/A	Refuge 3 Length (in)			

Total Cost: \$ 3000.00









N/A	Road 2 X Slope (%)	4.8 N/A	DWS 2 Offset (In)	N/A
N/A	Refuge 3 Length (in)	N/A N/A	Gutter 3 Ponding?	N/A
N/A	Refuge 3 Width (in)	N/A N/A	Gutter 3 Lip Ht (in)	N/A
N/A	Refuge 3 Slope (%)	N/A N/A	Gutter 3 Slope (%)	N/A
N/A	Refuge 3 XSlope (%)	N/A N/A	Gutter 3 XSlope (%)	N/A
N/A	Painted X Walk3?	N/A N/A	DWS 3 Provided?	N/A
N/A	X Walk 3 Direction	N/A N/A	DWS 3 Contrast?	N/A
N/A	X Walk 3 Width (in)	N/A N/A	DWS 3 Length (in)	N/A
N/A	Road 3 Slope (%)	N/A N/A	DWS 3 Full Width?	N/A
N/A	Road 3 XSlope (%)	N/A N/A	DWS 3 Offset (in)	N/A
Yes	Any Obstructions?	N/A N/A	Storm Grate/Utility Hazard?	N/A
N/A	Obstruction Type	N/A	Storm Grate/Utility Type	
		N/A		N/A
N/A	Surface Condition	Good		
		·		