

Access Compliance Report Public Rights-of-Way (Island Curb Cuts)



<u>Data</u>

N/A

N/A

Intersection ID: 17739 Main Street: E WOODLAWN RD Cross Street: SOUTH_BV Location: SW ADA ID: 9608D6F62143 **Curb Cut Type: IslandRefuge3** Initial Pass/Fail: Fail **Overall Compliance: No** Severity Score: 36.25

Codes/Mitigation Info/Possible Solution

Field Measurements/Component Compliance

Data Compliance

61.0 N/A Gutter 1 Ponding?

132.0 N/A Gutter 1 Lip Ht (In)

Description



Remove & Replace Entire Refuge.

Surveyor Notes:

Possible Solutions:

N/A

PROW/ADA:

N/A

Compliance

Description

Refuge 1 Length (In)

Refuge 1 Width (In)

Total Cost: 3000.00







Yes	Refuge 1 Slope (%)	2.5 N/	4	Gutter 1 Slope (%)	N/A
Yes	Refuge 1 X Slope (%)	2.8 N/	4	Gutter 1 X Slope (%)	N/A
N/A	Painted X Walk1?	Yes N/	4	DWS 1 Provided?	N/A
N/A	X Walk 1 Direction	To S N/	4	DWS 1 Contrast?	N/A
N/A	X Walk 1 Width (In)	103.0 N/	4	DWS 1 Length (In)	N/A
N/A	Road 1 Slope (%)	1.4 N/	4	DWS 1 Full Width?	N/A
N/A	Road 1 X Slope (%)	3.3 N//	4	DWS 1 Offset (In)	N/A
Yes	Refuge 2 Length (In)	70.0 N//	Δ.	Gutter 2 Ponding?	N/A
Yes	Refuge 2 Width (In)	96.0 N/A		Gutter 2 Lip Ht (In)	N/A
Yes	Refuge 2 Slope (%)	1.2 N//		Gutter 2 Slope (%)	N/A
Yes	Refuge 2 X Slope (%)	0.1 N//		Gutter 2 X Slope (%)	N/A
N/A	Painted X Walk2?	Yes N/	4	DWS 2 Provided?	N/A
N/A	X Walk 2 Direction	To SE N/		DWS 2 Contrast?	N/A
N/A	X Walk 2 Width (In)	112.0 N/	4	DWS 2 Length (In)	N/A
N/A	Road 2 Slope (%)	0.9 N/A	4	DWS 2 Full Width?	N/A
N/A	Road 2 X Slope (%)	3.2 N//	4	DWS 2 Offset (In)	N/A
Yes	Refuge 3 Length (in)	55.0 N//	4	Gutter 3 Ponding?	N/A
Yes	Refuge 3 Width (in)	100.0 N/		Gutter 3 Lip Ht (in)	N/A
Yes	Refuge 3 Slope (%)	1.6 N/	4	Gutter 3 Slope (%)	N/A
Yes	Refuge 3 XSlope (%)	0.5 N//	4	Gutter 3 XSlope (%)	N/A
N/A	Painted X Walk3?	Yes N/	4	DWS 3 Provided?	N/A
N/A	X Walk 3 Direction	To N N//	4	DWS 3 Contrast?	N/A
N/A	X Walk 3 Width (in)	112.0 N/	4	DWS 3 Length (in)	N/A
N/A	Road 3 Slope (%)	0.5 N/	4	DWS 3 Full Width?	N/A
N/A	Road 3 XSlope (%)	0.2 N//	4	DWS 3 Offset (in)	N/A
Yes	Any Obstructions?	N/A N/	4	Storm Grate/Utility Hazard?	N/A
N/A	Obstruction Type	N/A	4	Storm Grate/Utility Type	
		N/A			N/A
N/A	Surface Condition	Good			