

Access Compliance Report Public Rights-of-Way (Island Curb Cuts)



<u>Data</u>

N/A N/A N/A N/A N/A N/A

N/A N/A

N/A

N/A N/A N/A

N/A N/A

N/A N/A N/A N/A

N/A

Intersection ID: 10016569 Main Street: ALBEMARLE RD **Cross Street: CRESSWIND BV** Location: N ADA ID: 9694E92845C4 Curb Cut Type: MedianRefuge2 Initial Pass/Fail: Fail **Overall Compliance: No** Severity Score: 1.25

Codes/Mitigation Info/Possible Solution

Possible Solutions:

Field Measurements/Component Compliance



Remove & Replace Entire Refuge. Surveyor Notes: N/A

PROW/ADA:

N/A

| | i icia ivicasa | rements/e | Ollip | OHOH | Oomphane |
|-----------------------------|----------------------|-----------|-------|----------|---------------|
| Compliance Description Data | | | | pliance | Descriptio |
| Yes | Refuge 1 Length (In) | 96.5 | N/A | Gutter 1 | Ponding? |
| Yes | Refuge 1 Width (In) | 136.0 | N/A | Gutter 1 | Lip Ht (In) |
| Yes | Refuge 1 Slope (%) | 2.7 | N/A | Gutter 1 | Slope (%) |
| Yes | Refuge 1 X Slope (%) | 2.8 | N/A | Gutter 1 | X Slope (%) |
| N/A | Painted X Walk1? | Yes | N/A | DWS 1 | Provided? |
| N/A | X Walk 1 Direction | To E | N/A | DWS 1 | Contrast? |
| N/A | X Walk 1 Width (In) | 120.0 | N/A | DWS 1 | Length (In) |
| N/A | Road 1 Slope (%) | 3.2 | N/A | DWS 1 | Full Width? |
| N/A | Road 1 X Slope (%) | 2.8 | N/A | DWS 1 | Offset (In) |
| | | | | | |
| Yes | Refuge 2 Length (In) | 96.5 | N/A | Gutter 2 | 2 Ponding? |
| Yes | Refuge 2 Width (In) | 136.0 | N/A | Gutter 2 | 2 Lip Ht (In) |
| Yes | Refuge 2 Slope (%) | 2.0 | N/A | Gutter 2 | Slope (%) |
| Yes | Refuge 2 X Slope (%) | 2.2 | N/A | Gutter 2 | 2 X Slope (%) |
| N/A | Painted X Walk2? | Yes | N/A | DWS 2 | Provided? |
| N/A | X Walk 2 Direction | To W | N/A | DWS 2 | Contrast? |
| N/A | X Walk 2 Width (In) | 120.0 | N/A | DWS 2 | Length (In) |
| N/A | Road 2 Slope (%) | 2.2 | N/A | DWS 2 | Full Width? |
| N/A | Road 2 X Slope (%) | 1.5 | N/A | DWS 2 | Offset (In) |
| | | | | | |
| N/A | Refuge 3 Length (in) | N/A | N/A | Gutter 3 | 3 Ponding? |
| N/A | Refuge 3 Width (in) | N/A | N/A | Gutter 3 | B Lip Ht (in) |
| N/A | Refuge 3 Slope (%) | N/A | N/A | Gutter 3 | 3 Slope (%) |
| | | | | | |

Total Cost:

3000.00







| | rtolago o Longar (m) | ` | Callot of chang. | 14/74 |
|-----|-------------------------|-------|-----------------------------|-------|
| N/A | Refuge 3 Width (in) N/A | N/A | Gutter 3 Lip Ht (in) | N/A |
| N/A | Refuge 3 Slope (%) | N/A | Gutter 3 Slope (%) | N/A |
| N/A | Refuge 3 XSlope (%) | N/A | Gutter 3 XSlope (%) | N/A |
| N/A | Painted X Walk3? | N/A | DWS 3 Provided? | N/A |
| N/A | X Walk 3 Direction N/A | N/A | DWS 3 Contrast? | N/A |
| N/A | X Walk 3 Width (in) | N/A | DWS 3 Length (in) | N/A |
| N/A | Road 3 Slope (%) | N/A | DWS 3 Full Width? | N/A |
| N/A | Road 3 XSlope (%) | A N/A | DWS 3 Offset (in) | N/A |
| Yes | Any Obstructions? N/A | A N/A | Storm Grate/Utility Hazard? | N/A |
| N/A | Obstruction Type | N/A | Storm Grate/Utility Type | |
| | N/A | 4 | | N/A |
| N/A | Surface Condition Goo | d | | |
| | | | | |