

# Access Compliance Report

## Public Rights-of-Way

### (Island Curb Cuts)

Intersection ID: 8739	Main Street: N_TRYON_ST	Cross Street: W_EASTWAY_DR	Location: SE
ADA ID: 9A35AFB9BFB3	Curb Cut Type: IslandRefuge3	Initial Pass/Fail: Pass	Overall Compliance: No
Severity Score: 12.75			

#### Codes/Mitigation Info/Possible Solution

#### Field Measurements/Component Compliance



Possible Solutions:

**Grind Gutter Lip.**

Surveyor Notes:

**N/A**

PROW/ADA:

**N/A**

Total Cost:

**\$ 400.00**

Compliance	Description	Data	Compliance	Description	Data
Yes	Refuge 1 Length (In)	83.0	Yes	Gutter 1 Ponding?	No
Yes	Refuge 1 Width (In)	89.0	Yes	Gutter 1 Lip Ht (In)	0.0
Yes	Refuge 1 Slope (%)	3.9	Yes	Gutter 1 Slope (%)	2.4
Yes	Refuge 1 X Slope (%)	1.0	Yes	Gutter 1 X Slope (%)	0.8
N/A	Painted X Walk1?	Yes	Yes	DWS 1 Provided?	Yes
N/A	X Walk 1 Direction	To SE	Yes	DWS 1 Contrast?	Yes
N/A	X Walk 1 Width (In)	111.0	Yes	DWS 1 Length (In)	24.0
N/A	Road 1 Slope (%)	0.9	Yes	DWS 1 Full Width?	Yes
N/A	Road 1 X Slope (%)	1.3	Yes	DWS 1 Offset (In)	0.0
Yes	Refuge 2 Length (In)	344.0	Yes	Gutter 2 Ponding?	No
Yes	Refuge 2 Width (In)	94.0	No	Gutter 2 Lip Ht (In)	0.5
Yes	Refuge 2 Slope (%)	0.5	Yes	Gutter 2 Slope (%)	2.3
Yes	Refuge 2 X Slope (%)	2.0	Yes	Gutter 2 X Slope (%)	0.8
N/A	Painted X Walk2?	Yes	Yes	DWS 2 Provided?	Yes
N/A	X Walk 2 Direction	To SW	Yes	DWS 2 Contrast?	Yes
N/A	X Walk 2 Width (In)	109.0	Yes	DWS 2 Length (In)	24.0
N/A	Road 2 Slope (%)	0.8	Yes	DWS 2 Full Width?	Yes
N/A	Road 2 X Slope (%)	1.6	Yes	DWS 2 Offset (In)	0.0
Yes	Refuge 3 Length (in)	197.0	Yes	Gutter 3 Ponding?	No
Yes	Refuge 3 Width (in)	97.0	No	Gutter 3 Lip Ht (in)	0.5
Yes	Refuge 3 Slope (%)	2.2	Yes	Gutter 3 Slope (%)	2.3
Yes	Refuge 3 XSlope (%)	0.6	Yes	Gutter 3 XSlope (%)	1.0
N/A	Painted X Walk3?	Yes	Yes	DWS 3 Provided?	Yes
N/A	X Walk 3 Direction	To NW	Yes	DWS 3 Contrast?	Yes
N/A	X Walk 3 Width (in)	109.5	Yes	DWS 3 Length (in)	24.0
N/A	Road 3 Slope (%)	0.7	Yes	DWS 3 Full Width?	Yes
N/A	Road 3 XSlope (%)	0.5	Yes	DWS 3 Offset (in)	0.0
Yes	Any Obstructions?	No	N/A	Storm Grate/Utility Hazard?	No
N/A	Obstruction Type	N/A	N/A	Storm Grate/Utility Type	N/A
N/A	Surface Condition	Good			

