cole

Access Compliance Report Public Rights-of-Way (Island Curb Cuts)



	`		/			
Intersection ID: 16470	Main Street: E_INDEPENDENCE_BV	Cross S	Street: FARMINGD	ALE_DR	Location:	SW
ADA ID: A097900F35D6	Curb Cut Type: MedianRefuge2	Initial P	ass/Fail: Fail	Overall Compliance	: No Severity Score:	0
Codes/Mitigation Info/Possible Solution Field Measurements/Component Compliance						
	Possible Solutions:	(Compliance Descri		npliance Description	Data
	Remove & Replace Entire Refuge.	- ו	es Refuge 1 Length (I	n) 65.0 N/A	Gutter 1 Ponding?	N/A
	Stall	-	/es Refuge 1 Width (In		-	N/A
	3/	١	/es Refuge 1 Slope (%			N/A
# . A A		١	es Refuge 1 X Slope (Gutter 1 X Slope (%)	N/A
	1 C. 1	1	I/A Painted X Walk1?	Yes N/A	DWS 1 Provided?	N/A
		1	I/A X Walk 1 Direction	To NW N/A	DWS 1 Contrast?	N/A
5. /	Surveyor Notes:	1	I/A X Walk 1 Width (In) 121.0 N/A	DWS 1 Length (In)	N/A
	N/A	1	I/A Road 1 Slope (%)	0.6 N/A	DWS 1 Full Width?	N/A
CI-DIA A		1	I/A Road 1 X Slope (%	5) 1.8 N/A	DWS 1 Offset (In)	N/A
CLEAR		Y	′es Refuge 2 Length (I	n) 65.0 N/A	Gutter 2 Ponding?	N/A
			'es Refuge 2 Width (In		-	N/A
			'es Refuge 2 Slope (%	·		N/A
20-	PROW/ADA:		'es Refuge 2 X Slope (N/A
	N/A		I/A Painted X Walk2?	· /	DWS 2 Provided?	N/A
A A A A A A A A A A A A A A A A A A A		1	I/A X Walk 2 Direction	To SE N/A	DWS 2 Contrast?	N/A
0 0 0		1	I/A X Walk 2 Width (In) 120.0 N/A	DWS 2 Length (In)	N/A
		1	I/A Road 2 Slope (%)	2.1 N/A		N/A
		1	I/A Road 2 X Slope (%	b) 0.5 N/A	DWS 2 Offset (In)	N/A
		1	I/A Refuge 3 Length (ii	n) N/A N/A	Gutter 3 Ponding?	N/A
	Total Cost: \$ 30	00.00	I/A Refuge 3 Width (in	,	-	N/A
		1	I/A Refuge 3 Slope (%			N/A
		r	I/A Refuge 3 XSlope (N/A
		1	I/A Painted X Walk3?	N/A N/A	DWS 3 Provided?	N/A
			I/A X Walk 3 Direction	N/A N/A	DWS 3 Contrast?	N/A
		P	I/A X Walk 3 Width (in)) N/A N/A	DWS 3 Length (in)	N/A
		r	I/A Road 3 Slope (%)	N/A N/A		N/A
			I/A Road 3 XSlope (%		DWS 3 Offset (in)	N/A
		1	es Any Obstructions?	N/A N/A	Storm Grate/Utility Hazard?	N/A
		1 A	I/A Obstruction Type	N/A	Storm Grate/Utility Type	
		-		N/A		N/A
			I/A Surface Condition	Good		