cole

Access Compliance Report Public Rights-of-Way (Island Curb Cuts)



	•							
Intersection ID: 51054	Main Street: MULBERRY_CHURCH_RD	Cross	Cross Street: WESTPORT_RD			Location:	NE	
ADA ID: B16984766CAF	Curb Cut Type: MedianRefuge2	Initial	Pass	/Fail: Fail	Overall Complia	nce	: No Severity Score	: 0
Codes/Mitigation Info/Possible Solution Field Measurements/Component Compliance								
4.21	Possible Solutions:		Com	pliance Descriptio			npliance Description	Data
	Remove & Replace Entire Refuge		No	Refuge 1 Length (In)		N/A		N/A
A REAL PROPERTY AND A REAL PROPERTY A REAL PROPERTY AND A REAL PROPERTY A REAL PROPERTY AND A REAL PROPERTY A REAL PROPERTY AND A REAL PROPERTY AND A REAL PROPERTY AND A REAL PROPERTY A	Kelliove & Replace Elitile Relage	•	Yes	Refuge 1 Width (In)	136.0		•	N/A
			Yes	Refuge 1 Slope (%)		N/A	,	N/A
A CONTRACT OF A PAGE			Yes	Refuge 1 X Slope (%)		N/A	,	N/A
Le A the second second			N/A	Painted X Walk1?		N/A		N/A
			N/A	X Walk 1 Direction	To N	N/A		N/A
E & TEMPOLA	Surveyor Notes:		N/A	X Walk 1 Width (In)	119.0	N/A	DWS 1 Length (In)	N/A
	N/A		N/A	Road 1 Slope (%)	1.8	N/A		N/A
			N/A	Road 1 X Slope (%)	3.2	N/A	DWS 1 Offset (In)	N/A
				,			. ,	
			No	Refuge 2 Length (In)	30.0	N/A	Gutter 2 Ponding?	N/A
	PROW/ADA: N/A		Yes	Refuge 2 Width (In)	136.0	N/A	-	N/A
			Yes	Refuge 2 Slope (%)	0.9	N/A	Gutter 2 Slope (%)	N/A
			Yes	Refuge 2 X Slope (%)	2.1	N/A		N/A
			N/A	Painted X Walk2?	Yes	N/A	DWS 2 Provided?	N/A
			N/A	X Walk 2 Direction	To S	N/A	DWS 2 Contrast?	N/A
	Line a		N/A	X Walk 2 Width (In)	121.0	N/A	DWS 2 Length (In)	N/A
			N/A	Road 2 Slope (%)	0.8	N/A	DWS 2 Full Width?	N/A
			N/A	Road 2 X Slope (%)	3.3	N/A	DWS 2 Offset (In)	N/A
			N/A	Refuge 3 Length (in)	N/A	N/A	Gutter 3 Ponding?	N/A
	Total Cost: \$ 30	00.00	N/A	Refuge 3 Width (in)	N/A	N/A	-	N/A
	•••••••••••••••••••••••••••••••••••••••		N/A	Refuge 3 Slope (%)	N/A	N/A		N/A
			N/A	Refuge 3 XSlope (%)		N/A	1 ()	N/A
			N/A	Painted X Walk3?		N/A		N/A
			N/A	X Walk 3 Direction	N/A	N/A		N/A
			N/A	X Walk 3 Width (in)		N/A		N/A
			N/A	Road 3 Slope (%)	N/A	N/A	o ()	N/A
			N/A	Road 3 XSlope (%)	N/A	N/A	DWS 3 Offset (in)	N/A
			Yes	Any Obstructions?		N/A		N/A
			N/A	Obstruction Type		N/A	•	
					N/A		5 51	N/A
	HAMPEN CONTRACTOR	A TH	N/A	Surface Condition	Good			