

Access Compliance Report

Public Rights-of-Way

(Island Curb Cuts)

Intersection ID: 12640	Main Street: W_MOREHEAD_ST	Cross Street: WILKINSON_BV	Location: NW
ADA ID: B2480069C652	Curb Cut Type: IslandRefuge3	Initial Pass/Fail: Pass	Overall Compliance: No
Severity Score: 5.25			
Codes/Mitigation Info/Possible Solution		Field Measurements/Component Compliance	



Possible Solutions:

Remove & Replace Detectable Warning System.


Surveyor Notes:

N/A

PROW/ADA:

N/A

Total Cost: \$ 800.00



Compliance	Description	Data	Compliance	Description	Data
Yes	Refuge 1 Length (In)	112.0	Yes	Gutter 1 Ponding?	No
Yes	Refuge 1 Width (In)	98.0	Yes	Gutter 1 Lip Ht (In)	0.0
Yes	Refuge 1 Slope (%)	1.0	Yes	Gutter 1 Slope (%)	1.6
Yes	Refuge 1 X Slope (%)	0.2	Yes	Gutter 1 X Slope (%)	0.5
N/A	Painted X Walk1?	Yes	Yes	DWS 1 Provided?	Yes
N/A	X Walk 1 Direction	To W	Yes	DWS 1 Contrast?	Yes
N/A	X Walk 1 Width (In)	110.0	Yes	DWS 1 Length (In)	24.0
N/A	Road 1 Slope (%)	0.4	Yes	DWS 1 Full Width?	Yes
N/A	Road 1 X Slope (%)	2.2	Yes	DWS 1 Offset (In)	0.0
Yes	Refuge 2 Length (In)	147.0	Yes	Gutter 2 Ponding?	No
Yes	Refuge 2 Width (In)	100.0	Yes	Gutter 2 Lip Ht (In)	0.0
Yes	Refuge 2 Slope (%)	2.6	Yes	Gutter 2 Slope (%)	0.7
Yes	Refuge 2 X Slope (%)	1.2	Yes	Gutter 2 X Slope (%)	1.6
N/A	Painted X Walk2?	Yes	Yes	DWS 2 Provided?	Yes
N/A	X Walk 2 Direction	To S	Yes	DWS 2 Contrast?	Yes
N/A	X Walk 2 Width (In)	113.0	Yes	DWS 2 Length (In)	24.0
N/A	Road 2 Slope (%)	1.5	Yes	DWS 2 Full Width?	Yes
N/A	Road 2 X Slope (%)	1.0	Yes	DWS 2 Offset (In)	0.0
Yes	Refuge 3 Length (in)	125.0	Yes	Gutter 3 Ponding?	No
Yes	Refuge 3 Width (in)	98.0	Yes	Gutter 3 Lip Ht (in)	0.0
Yes	Refuge 3 Slope (%)	3.7	Yes	Gutter 3 Slope (%)	1.7
Yes	Refuge 3 XSlope (%)	1.4	Yes	Gutter 3 XSlope (%)	1.3
N/A	Painted X Walk3?	Yes	Yes	DWS 3 Provided?	Yes
N/A	X Walk 3 Direction	To E	Yes	DWS 3 Contrast?	Yes
N/A	X Walk 3 Width (in)	113.0	Yes	DWS 3 Length (in)	24.0
N/A	Road 3 Slope (%)	0.9	Yes	DWS 3 Full Width?	Yes
N/A	Road 3 XSlope (%)	1.9	No	DWS 3 Offset (in)	2.5
Yes	Any Obstructions?	No	N/A	Storm Grate/Utility Hazard?	No
N/A	Obstruction Type	N/A	N/A	Storm Grate/Utility Type	N/A
N/A	Surface Condition	Good			