cole

Access Compliance Report Public Rights-of-Way (Island Curb Cuts)



Intersection ID: 7243	Main Street: N_GRAHAM_ST	Cross	Stro	et: S_I-85_EXIT	40 RA		Location:	S
ADA ID: C4C00BE36D16	Curb Cut Type: IslandRefuge2	Initial	Pass	Fail: Fail	Overall Complia			1.25
Codes/Mit			Field	Measurements/C	omp	ponent Compliance		
Real Cont	Possible Solutions:		Com	pliance Descript	tion Data	Com	npliance Description	Data
	Remove & Replace Entire Refuge		Yes	Refuge 1 Length (In)) 179.0	N/A	Gutter 1 Ponding?	N/A
			Yes	Refuge 1 Width (In)	94.5	N/A	Gutter 1 Lip Ht (In)	N/A
			Yes	Refuge 1 Slope (%)	3.0	N/A	Gutter 1 Slope (%)	N/A
			Yes	Refuge 1 X Slope (%	6) 2.5	N/A	Gutter 1 X Slope (%)	N/A
NA Xee	A CARAGE AND A CAR		N/A	Painted X Walk1?	Yes	N/A	DWS 1 Provided?	N/A
3/0000			N/A	X Walk 1 Direction	To NE	N/A	DWS 1 Contrast?	N/A
	Surveyor Notes:		N/A	X Walk 1 Width (In)	107.5		8 ()	N/A
	N/A		N/A	Road 1 Slope (%)	3.0	N/A	DWS 1 Full Width?	N/A
S Jest Hall and			N/A	Road 1 X Slope (%)	0.1	N/A	DWS 1 Offset (In)	N/A
			Yes	Refuge 2 Length (In)) 229.0	N/A	Gutter 2 Ponding?	N/A
			Yes	Refuge 2 Width (In)		N/A	-	N/A
			Yes	Refuge 2 Slope (%)	1.6	N/A		N/A
	PROW/ADA:		Yes	Refuge 2 X Slope (%	6) 2.3	N/A	Gutter 2 X Slope (%)	N/A
			N/A	Painted X Walk2?			DWS 2 Provided?	N/A
	at the second se		N/A	X Walk 2 Direction	To W	N/A	DWS 2 Contrast?	N/A
			N/A	X Walk 2 Width (In)	112.0	N/A	DWS 2 Length (In)	N/A
			N/A	Road 2 Slope (%)	2.5	N/A	DWS 2 Full Width?	N/A
			N/A	Road 2 X Slope (%)	4.6	N/A	DWS 2 Offset (In)	N/A
			N/A	Refuge 3 Length (in)) N/A	N/A	Gutter 3 Ponding?	N/A
	Total Cost: \$ 30	00.00	N/A	Refuge 3 Width (in)		N/A	5	N/A
			N/A	Refuge 3 Slope (%)			Gutter 3 Slope (%)	N/A
			N/A	Refuge 3 XSlope (%		N/A		N/A
			N/A	Painted X Walk3?		N/A	,	N/A
		7	N/A	X Walk 3 Direction	N/A	N/A	DWS 3 Contrast?	N/A
		//	N/A	X Walk 3 Width (in)	N/A	N/A	DWS 3 Length (in)	N/A
			N/A	Road 3 Slope (%)			DWS 3 Full Width?	N/A
				Road 3 XSlope (%)			DWS 3 Offset (in)	N/A
		-		Any Obstructions?	N/A	N/A	Storm Grate/Utility Hazard?	N/A
		1	N/A	Obstruction Type		N/A	Storm Grate/Utility Type	
		-			N/A			N/A
			N/A	Surface Condition	Good	I		