cole

Access Compliance Report Public Rights-of-Way (Island Curb Cuts)



Intersection ID: 25815	Main Street: REA_RD	Cross	Cross Street: PINEVILLE-MATTHEWS_RD			Location:	NE
ADA ID: C53C2FFBAF0F	Curb Cut Type: IslandRefuge3	Initial	Pass/Fail:	Fail Ove	rall Compliance	: No Severity Score:	35
Codes/Mitigation Info/Possible Solution Field Measurements/Component Compliance							
	Possible Solutions:		Compliance		Data Cor		Data
	Remove & Replace Entire Refuge	`		e 1 Length (In)		Gutter 1 Ponding?	N/A
	Remove a Replace Entire Relage		-	e 1 Width (In)		Gutter 1 Lip Ht (In)	N/A
	and the second se			e 1 Slope (%)		Gutter 1 Slope (%)	N/A
				e 1 X Slope (%)		Gutter 1 X Slope (%)	N/A
	AR AN AND A AND			d X Walk1?	Yes N/A		N/A
				k 1 Direction	To SE N/A	DWS 1 Contrast?	N/A
6	Surveyor Notes:		N/A X Wall	k 1 Width (In)	112.0 N/A	DWS 1 Length (In)	N/A
	N/A		N/A Road	1 Slope (%)		DWS 1 Full Width?	N/A
				1 X Slope (%)	1.9 N/A	DWS 1 Offset (In)	N/A
13 1				• • •			
PINEVILLE-MATTHEWS_RD			Yes Refuge	e 2 Length (In)	66.0 N/A	Gutter 2 Ponding?	N/A
PINEMIE	10			e 2 Width (In)		Gutter 2 Lip Ht (In)	N/A
				e 2 Slope (%)	0.3 N/A		N/A
	PROW/ADA:		-	e 2 X Slope (%)	2.6 N/A		N/A
	N/A		-	d X Walk2?	Yes N/A		N/A
E I A			N/A X Wall	k 2 Direction	To NE N/A		N/A
s THATING			N/A X Wall	k 2 Width (In)	114.0 N/A	DWS 2 Length (In)	N/A
			N/A Road 2	2 Slope (%)	0.6 N/A		N/A
				2 X Slope (%)	1.1 N/A	DWS 2 Offset (In)	N/A
			Yes Refuge	e 3 Length (in)	36.0 N/A	Gutter 3 Ponding?	N/A
	Total Cost: \$ 30	000.00	Yes Refuge	e 3 Width (in)	96.0 N/A	Gutter 3 Lip Ht (in)	N/A
				e 3 Slope (%)	0.7 N/A	Gutter 3 Slope (%)	N/A
			Yes Refuge	e 3 XSlope (%)	2.0 N/A	Gutter 3 XSlope (%)	N/A
			N/A Painte	d X Walk3?	Yes N/A	DWS 3 Provided?	N/A
			N/A X Wall	k 3 Direction	To NW N/A	DWS 3 Contrast?	N/A
		-	N/A X Wall	k 3 Width (in)	114.0 N/A	DWS 3 Length (in)	N/A
			N/A Road	3 Slope (%)	0.1 N/A	DWS 3 Full Width?	N/A
			N/A Road	3 XSlope (%)	3.0 N/A	DWS 3 Offset (in)	N/A
	And the second s		Yes Any O	bstructions?	N/A N/A	Storm Grate/Utility Hazard?	N/A
and the second second			N/A Obstru	uction Type	N/A	Storm Grate/Utility Type	
		A A A A A A A A A A A A A A A A A A A			N/A		N/A
		- A	N/A Surfac	e Condition	Good		