


Access Compliance Report

Public Rights-of-Way

(Island Curb Cuts)

Intersection ID: 7770	Main Street: E_ARROWHEAD_DR	Cross Street: N_TRYON_ST	Location:	N
ADA ID: C713BB9F9E10	Curb Cut Type: MedianRefuge2	Initial Pass/Fail: Pass	Overall Compliance: No	Severity Score: 15.25

Codes/Mitigation Info/Possible Solution			Field Measurements/Component Compliance			
	Possible Solutions:		Compliance	Description	Data	
	Remove & Replace Detectable Warning System. Grind Gutter Lip.		Yes	Refuge 1 Length (In)	92.5	No
			Yes	Refuge 1 Width (In)	120.0	No
			Yes	Refuge 1 Slope (%)	1.9	Yes
			Yes	Refuge 1 X Slope (%)	0.4	Yes
			N/A	Painted X Walk1?	Yes	Yes
			N/A	X Walk 1 Direction	To E	Yes
			N/A	X Walk 1 Width (In)	120.0	Yes
			N/A	Road 1 Slope (%)	0.0	Yes
			N/A	Road 1 X Slope (%)	2.5	No
<p>Surveyor Notes:</p> <p>N/A</p>			Yes	Refuge 2 Length (In)	109.0	Yes
			Yes	Refuge 2 Width (In)	120.0	Yes
			Yes	Refuge 2 Slope (%)	3.1	Yes
			Yes	Refuge 2 X Slope (%)	0.5	Yes
			N/A	Painted X Walk2?	No	Yes
			N/A	X Walk 2 Direction	To W	Yes
			N/A	X Walk 2 Width (In)	N/A	Yes
			N/A	Road 2 Slope (%)	0.5	Yes
			N/A	Road 2 X Slope (%)	0.2	Yes
			N/A	Refuge 3 Length (in)	N/A	N/A
<p>PROW/ADA:</p> <p>N/A</p>			N/A	Refuge 3 Width (in)	N/A	N/A
			N/A	Refuge 3 Slope (%)	N/A	N/A
			N/A	Refuge 3 XSlope (%)	N/A	N/A
			N/A	Painted X Walk3?	No	N/A
			N/A	X Walk 3 Direction	N/A	N/A
			N/A	X Walk 3 Width (in)	N/A	N/A
			N/A	Road 3 Slope (%)	N/A	N/A
			N/A	Road 3 XSlope (%)	N/A	N/A
			Yes	Any Obstructions?	No	N/A
			N/A	Obstruction Type	N/A	N/A
<p>Total Cost:</p> <p>\$ 1000.00</p>			N/A	Surface Condition	Good	N/A

