## cole

## Access Compliance Report Public Rights-of-Way (Island Curb Cuts)



	•			-				
Intersection ID: 10020730	0 Main Street: BEATTIES_FORD_RD C			oss Street: N/A				NW
ADA ID: CBC872FDBC85	Curb Cut Type: MedianRefuge2	Initia	tial Pass/Fail: Pass Overall Compliance: No				No Severity Sco	re: 10.25
Codes/Miti	Field Measurements/Component Compliance							
BRAN LA LANA	Possible Solutions:		Comp	oliance Descrip			pliance Description	Data
	Remove & Replace Entire Refuge	).	No	Refuge 1 Length (li	n) <b>35.0</b>	Yes	Gutter 1 Ponding?	No
	Remove & Replace Gutter.	-		Refuge 1 Width (In)		Yes	Gutter 1 Lip Ht (In)	0.0
			Yes	Refuge 1 Slope (%	b) <b>3.3</b>	No	Gutter 1 Slope (%)	7.6
			Yes	Refuge 1 X Slope (	(%) 0.9	Yes	Gutter 1 X Slope (%)	0.8
			N/A	Painted X Walk1?	No	No	DWS 1 Provided?	Yes
	All Sec		N/A	X Walk 1 Direction	To NE	N/A	DWS 1 Contrast?	Yes
6. 6	Surveyor Notes:		N/A	X Walk 1 Width (In)	) <b>N/A</b>	N/A	DWS 1 Length (In)	24.0
	N/A		N/A	Road 1 Slope (%)	0.9	N/A	DWS 1 Full Width?	Yes
				Road 1 X Slope (%	5. <b>9</b>	N/A	DWS 1 Offset (In)	0.0
					,		ζ,	
			No	Refuge 2 Length (II	n) <b>32.0</b>	Yes	Gutter 2 Ponding?	No
			Yes	Refuge 2 Width (In	95.0	Yes	Gutter 2 Lip Ht (In)	0.0
				Refuge 2 Slope (%		Yes		0.9
	PROW/ADA:			Refuge 2 X Slope (		Yes	Gutter 2 X Slope (%)	1.7
	N/A			Painted X Walk2?		No	DWS 2 Provided?	Yes
			N/A	X Walk 2 Direction	To SW	N/A	DWS 2 Contrast?	Yes
an size - in the second			N/A	X Walk 2 Width (In)	) <b>N/A</b>	N/A	DWS 2 Length (In)	24.0
			N/A	Road 2 Slope (%)	1.4	N/A	DWS 2 Full Width?	Yes
			N/A	Road 2 X Slope (%	b) <b>1.4</b>	N/A	DWS 2 Offset (In)	0.0
			N/A	Refuge 3 Length (ir		N/A	0	N/A
	Total Cost: \$ 3	750.00	N/A	Refuge 3 Width (in)			Gutter 3 Lip Ht (in)	N/A
				Refuge 3 Slope (%			Gutter 3 Slope (%)	N/A
				Refuge 3 XSlope (9	%) N/A	N/A	Gutter 3 XSlope (%)	N/A
				Painted X Walk3?	N/A		DWS 3 Provided?	N/A
				X Walk 3 Direction	N/A	N/A	DWS 3 Contrast?	N/A
				X Walk 3 Width (in)	,	N/A	DWS 3 Length (in)	N/A
			N/A	Road 3 Slope (%)	N/A	N/A	DWS 3 Full Width?	N/A
			N/A	Road 3 XSlope (%)	) <b>N/A</b>	N/A	DWS 3 Offset (in)	N/A
				Any Obstructions?	No	N/A	Storm Grate/Utility Hazard?	No
			N/A	Obstruction Type		N/A	Storm Grate/Utility Type	
					N/A			N/A
			N/A	Surface Condition	Good			