

Access Compliance Report

Public Rights-of-Way

(Island Curb Cuts)

| | | | |
|---|------------------------------|---|------------------------|
| Intersection ID: 4279 | Main Street: LAKEVIEW_RD | Cross Street: REAMES_RD | Location: NE |
| ADA ID: D793B0939CF1 | Curb Cut Type: IslandRefuge3 | Initial Pass/Fail: Pass | Overall Compliance: No |
| Codes/Mitigation Info/Possible Solution | | Field Measurements/Component Compliance | |
| Severity Score: 20.25 | | | |



Possible Solutions:

**Install Detectable Warning System.
Fix Gutter Ponding. Remove &
Replace Gutter.**

Surveyor Notes:

N/A

PROW/ADA:

N/A

Total Cost: \$ 2455.00

| Compliance | Description | Data | Compliance | Description | Data |
|------------|----------------------|-------|------------|-----------------------------|------|
| Yes | Refuge 1 Length (In) | 96.0 | No | Gutter 1 Ponding? | Yes |
| Yes | Refuge 1 Width (In) | 72.0 | Yes | Gutter 1 Lip Ht (In) | 0.0 |
| Yes | Refuge 1 Slope (%) | 1.1 | Yes | Gutter 1 Slope (%) | 1.4 |
| Yes | Refuge 1 X Slope (%) | 1.5 | Yes | Gutter 1 X Slope (%) | 0.9 |
| N/A | Painted X Walk1? | Yes | No | DWS 1 Provided? | No |
| N/A | X Walk 1 Direction | To SE | N/A | DWS 1 Contrast? | N/A |
| N/A | X Walk 1 Width (In) | 85.0 | N/A | DWS 1 Length (In) | N/A |
| N/A | Road 1 Slope (%) | 1.0 | N/A | DWS 1 Full Width? | N/A |
| N/A | Road 1 X Slope (%) | 0.4 | N/A | DWS 1 Offset (In) | N/A |
| Yes | Refuge 2 Length (In) | 120.0 | No | Gutter 2 Ponding? | Yes |
| Yes | Refuge 2 Width (In) | 72.0 | Yes | Gutter 2 Lip Ht (In) | 0.0 |
| Yes | Refuge 2 Slope (%) | 2.2 | Yes | Gutter 2 Slope (%) | 2.3 |
| Yes | Refuge 2 X Slope (%) | 0.5 | Yes | Gutter 2 X Slope (%) | 1.1 |
| N/A | Painted X Walk2? | No | No | DWS 2 Provided? | No |
| N/A | X Walk 2 Direction | To N | N/A | DWS 2 Contrast? | N/A |
| N/A | X Walk 2 Width (In) | N/A | N/A | DWS 2 Length (In) | N/A |
| N/A | Road 2 Slope (%) | 0.6 | N/A | DWS 2 Full Width? | N/A |
| N/A | Road 2 X Slope (%) | 1.8 | N/A | DWS 2 Offset (In) | N/A |
| Yes | Refuge 3 Length (in) | 105.0 | No | Gutter 3 Ponding? | Yes |
| Yes | Refuge 3 Width (in) | 75.0 | Yes | Gutter 3 Lip Ht (in) | 0.0 |
| Yes | Refuge 3 Slope (%) | 0.1 | Yes | Gutter 3 Slope (%) | 1.3 |
| Yes | Refuge 3 XSlope (%) | 1.9 | No | Gutter 3 XSlope (%) | 2.1 |
| N/A | Painted X Walk3? | No | No | DWS 3 Provided? | No |
| N/A | X Walk 3 Direction | To W | N/A | DWS 3 Contrast? | N/A |
| N/A | X Walk 3 Width (in) | N/A | N/A | DWS 3 Length (in) | N/A |
| N/A | Road 3 Slope (%) | 2.0 | N/A | DWS 3 Full Width? | N/A |
| N/A | Road 3 XSlope (%) | 1.5 | N/A | DWS 3 Offset (in) | N/A |
| Yes | Any Obstructions? | N/A | N/A | Storm Grate/Utility Hazard? | No |
| N/A | Obstruction Type | | N/A | Storm Grate/Utility Type | |
| | | N/A | | | N/A |
| N/A | Surface Condition | Good | | | |

