

Access Compliance Report Public Rights-of-Way (Island Curb Cuts)



<u>Data</u>

N/A

Description

Intersection ID: 51379 Main Street: BROADRICK BV **Cross Street: UNIVERSITY CITY BV** Location: N ADA ID: EB6623D3CB92 Curb Cut Type: MedianRefuge2 Initial Pass/Fail: Fail **Overall Compliance: No Severity Score:** 25

Codes/Mitigation Info/Possible Solution

Field Measurements/Component Compliance



Remove & Replace Entire Refuge.

Surveyor Notes:

Possible Solutions:

N/A

PROW/ADA:

N/A

Compliance Description		Data Complian		Description
Yes	Refuge 1 Length (In)	118.0 N/	/A Gutter 1	Ponding?
Yes	Refuge 1 Width (In)	96.0 N/	/A Gutter 1	Lip Ht (In)
No	Refuge 1 Slope (%)	10.0 N/	/A Gutter 1	Slope (%)
Yes	Refuge 1 X Slope (%)	0.1 N/	/A Gutter 1	X Slope (%)
N/A	Painted X Walk1?	Yes N	A DWS 1	Provided?
N/A	X Walk 1 Direction	To SW N/	A DWS 1	Contrast?
N/A	X Walk 1 Width (In)	76.0 N/	A DWS 1	Length (In)
N/A	Road 1 Slope (%)	1.0 N/	A DWS 1	Full Width?
N/A	Road 1 X Slope (%)	1.1 N/	A DWS 1	Offset (In)
Yes	Refuge 2 Length (In)	118.0 N/	A Gutter 2	Ponding?
Yes	Refuge 2 Width (In)	96.0 N/	A Gutter 2	Lip Ht (In)
No	Refuge 2 Slope (%)	10.0 N/	A Gutter 2	Slope (%)
Yes	Refuge 2 X Slope (%)	1.0 N/	A Gutter 2	X Slope (%)
N/A	Painted X Walk2?	Yes N/	A DWS 2	Provided?
N/A	X Walk 2 Direction	To NE N/	A DWS 2	Contrast?
N/A	X Walk 2 Width (In)	76.0 N/	A DWS 2	Length (In)
N/A	Road 2 Slope (%)	0.8 N/	A DWS 2	Full Width?
N/A	Road 2 X Slope (%)	1.0 N/	A DWS 2	Offset (In)
N/A	Refuge 3 Length (in)	N/A N/	A Gutter 3	Ponding?
N/A	Pofugo 3 Width (in)	N/A N/	/A Guttor 3	Lin Ht (in)

Total Cost: 3000.00







N/A	Refuge 3 Length (in)	N/A	N/A	Gutter 3 Ponding?	N/A
N/A	Refuge 3 Width (in)	N/A	N/A	Gutter 3 Lip Ht (in)	N/A
N/A	Refuge 3 Slope (%)	N/A	N/A	Gutter 3 Slope (%)	N/A
N/A	Refuge 3 XSlope (%)	N/A	N/A	Gutter 3 XSlope (%)	N/A
N/A	Painted X Walk3?	No	N/A	DWS 3 Provided?	N/A
N/A	X Walk 3 Direction	N/A	N/A	DWS 3 Contrast?	N/A
N/A	X Walk 3 Width (in)	N/A	N/A	DWS 3 Length (in)	N/A
N/A	Road 3 Slope (%)	N/A	N/A	DWS 3 Full Width?	N/A
N/A	Road 3 XSlope (%)	N/A	N/A	DWS 3 Offset (in)	N/A
Yes	Any Obstructions?	N/A	N/A	Storm Grate/Utility Hazard?	N/A
N/A	Obstruction Type		N/A	Storm Grate/Utility Type	
		N/A			N/A
N/A	Surface Condition	Good			