

Access Compliance Report Public Rights-of-Way (Island Curb Cuts)



<u>Data</u>

Intersection ID: 53757 Main Street: JOHNSTON_OEHLER_RD Cross Street: N/A Location: E

ADA ID: F17FC43DE407 Curb Cut Type: MedianRefuge2 Initial Pass/Fail: Fail Overall Compliance: No Severity Score: 0

Compliance

Description

| Codes/Mitigation Info/Possible Solution | 1 |
|---|---|
|---|---|

Field Measurements/Component Compliance

Data Compliance

Description



Possible Solutions:

Remove & Replace Entire Refuge.

Surveyor Notes:

N/A

PROW/ADA:

Total Cost: \$ 3000.00







| Yes | Refuge 1 Length (In) | 46.0 N | I/A | Gutter 1 Ponding? | N/A |
|-----|----------------------|---------|-----|-----------------------------|-----|
| Yes | Refuge 1 Width (In) | | I/A | Gutter 1 Lip Ht (In) | N/A |
| Yes | Refuge 1 Slope (%) | | I/A | Gutter 1 Slope (%) | N/A |
| Yes | Refuge 1 X Slope (%) | | I/A | Gutter 1 X Slope (%) | N/A |
| N/A | Painted X Walk1? | Yes N | I/A | DWS 1 Provided? | N/A |
| N/A | X Walk 1 Direction | To S N | I/A | DWS 1 Contrast? | N/A |
| N/A | X Walk 1 Width (In) | 111.0 N | I/A | DWS 1 Length (In) | N/A |
| N/A | Road 1 Slope (%) | 0.1 N | I/A | DWS 1 Full Width? | N/A |
| N/A | Road 1 X Slope (%) | 3.2 N | I/A | DWS 1 Offset (In) | N/A |
| | | | | | |
| Yes | Refuge 2 Length (In) | 46.0 N | I/A | Gutter 2 Ponding? | N/A |
| Yes | Refuge 2 Width (In) | 118.0 N | I/A | Gutter 2 Lip Ht (In) | N/A |
| Yes | Refuge 2 Slope (%) | 0.1 N | I/A | Gutter 2 Slope (%) | N/A |
| Yes | Refuge 2 X Slope (%) | 3.7 N | I/A | Gutter 2 X Slope (%) | N/A |
| N/A | Painted X Walk2? | Yes N | I/A | DWS 2 Provided? | N/A |
| N/A | X Walk 2 Direction | To N N | I/A | DWS 2 Contrast? | N/A |
| N/A | X Walk 2 Width (In) | 111.0 N | I/A | DWS 2 Length (In) | N/A |
| N/A | Road 2 Slope (%) | 0.3 N | I/A | DWS 2 Full Width? | N/A |
| N/A | Road 2 X Slope (%) | 3.2 N | I/A | DWS 2 Offset (In) | N/A |
| | | | | 0 " 0 0 " 0 | |
| N/A | Refuge 3 Length (in) | N/A N | | Gutter 3 Ponding? | N/A |
| N/A | Refuge 3 Width (in) | N/A N | | Gutter 3 Lip Ht (in) | N/A |
| N/A | Refuge 3 Slope (%) | | I/A | Gutter 3 Slope (%) | N/A |
| N/A | Refuge 3 XSlope (%) | | I/A | Gutter 3 XSlope (%) | N/A |
| N/A | Painted X Walk3? | | I/A | DWS 3 Provided? | N/A |
| N/A | X Walk 3 Direction | | I/A | DWS 3 Contrast? | N/A |
| N/A | X Walk 3 Width (in) | | I/A | DWS 3 Length (in) | N/A |
| N/A | Road 3 Slope (%) | N/A N | | DWS 3 Full Width? | N/A |
| N/A | Road 3 XSlope (%) | N/A N | | DWS 3 Offset (in) | N/A |
| Yes | Any Obstructions? | | I/A | Storm Grate/Utility Hazard? | N/A |
| N/A | Obstruction Type | | I/A | Storm Grate/Utility Type | |
| | | N/A | | | N/A |
| N/A | Surface Condition | Good | | | |
| | | | | | |