## cole

## Access Compliance Report Public Rights-of-Way (Island Curb Cuts)



Intersection ID: 52767 Main Street: OUTLETS_BV		Cross Street: NEW_FASHION_WY		Location:	NE	
ADA ID: FF21356E0A2B	Curb Cut Type: MedianRefuge2	nitial Pas	s/Fail: Fail Ove	rall Compliance	: No Severity Score:	0
Codes/Mitigation Info/Possible Solution Field Measurements/Component Compliance						
	Possible Solutions:	Cor	npliance Description	Data Con		Data
	Remove & Replace Entire Refuge.	_	Refuge 1 Length (In)		Gutter 1 Ponding?	N/A
	Remove & Replace Entire Relage.	Yes			Gutter 1 Lip Ht (In)	N/A
4 61.	6.	Yes			Gutter 1 Slope (%)	N/A
	and the second s	Yes			Gutter 1 X Slope (%)	N/A
		N/A		No N/A	,	N/A
		N/A		To NW N/A		N/A
Q & & ANON	Surveyor Notes:	N/A	X Walk 1 Width (In)		DWS 1 Length (In)	N/A
E av Ele	N/A	N/A	Road 1 Slope (%)		DWS 1 Full Width?	N/A
	and the second	N/A		4.6 N/A	DWS 1 Offset (In)	N/A
2	and the second se					
6	10 million	Yes	Refuge 2 Length (In)	107.5 N/A	Gutter 2 Ponding?	N/A
1 B B 2		Yes	Refuge 2 Width (In)	121.0 N/A	Gutter 2 Lip Ht (In)	N/A
		Yes	Refuge 2 Slope (%)	0.8 N/A	Gutter 2 Slope (%)	N/A
	PROW/ADA:	Yes	Refuge 2 X Slope (%)	0.1 N/A	Gutter 2 X Slope (%)	N/A
	N/A	N/A	Painted X Walk2?	No N/A	DWS 2 Provided?	N/A
		N/A	X Walk 2 Direction	To SE N/A	DWS 2 Contrast?	N/A
		N/A	X Walk 2 Width (In)	N/A N/A	DWS 2 Length (In)	N/A
		N/A	Road 2 Slope (%)	0.1 N/A	DWS 2 Full Width?	N/A
		N/A	Road 2 X Slope (%)	5.5 N/A	DWS 2 Offset (In)	N/A
		N/A	Refuge 3 Length (in)	N/A N/A	Gutter 3 Ponding?	N/A
	Total Cost: \$ 3000	0.00 N/A	Refuge 3 Width (in)	N/A N/A	Gutter 3 Lip Ht (in)	N/A
		N/A	Refuge 3 Slope (%)	N/A N/A	Gutter 3 Slope (%)	N/A
		N/A	Refuge 3 XSlope (%)	N/A N/A	Gutter 3 XSlope (%)	N/A
		N/A	Painted X Walk3?	N/A N/A	DWS 3 Provided?	N/A
		N/A	X Walk 3 Direction	N/A N/A	DWS 3 Contrast?	N/A
1 Phone Hill The Contract of C		N/A	X Walk 3 Width (in)	N/A N/A	DWS 3 Length (in)	N/A
		N/A	Road 3 Slope (%)	N/A N/A	DWS 3 Full Width?	N/A
		N/A	Road 3 XSlope (%)	N/A N/A	DWS 3 Offset (in)	N/A
		Yes	Any Obstructions?	N/A N/A	Storm Grate/Utility Hazard?	N/A
		N/A	Obstruction Type	N/A	Storm Grate/Utility Type	
		1		N/A		N/A
		N/A	Surface Condition	Good		