# Access Compliance Report
# Public Rights-of-Way
# (Curb Ramps)

**cole**

**CHARLOTTE**

| | | | |
|---|---|---|---|
| **Intersection ID:** 26386 | **Main Street:** OVER_STREAM_LN | **Cross Street:** PROVIDENCE_HILLS_DR | **Location:** E |
| **ADA ID:** 256BB2E28807 | **Ramp Type:** BlendTrans2 | **Initial Pass/Fail:** Pass | **Overall Compliance:** No | **Severity Score:** 0 |

| Codes/Mitigation Info/Possible Solution | Field Measurements/Component Compliance |
|---|---|



**Possible Solutions:**

**Remove & Replace Curb Ramp With Two New Directional Ramps or Equivalent.**

**Surveyor Notes:**

**N/A**

**PROW/ADA:**

**Not Found, R304.2.3, R305.2**

| | | |
|---|---|---|
| Street 1 Name | **PROVIDENCE HILLS DR** |
| Stop Condition-Street 1 | **None** |
| Street 2 Name | **N/A** |
| Stop Condition-Street 2 | **N/A** |

Total Cost:  $  3200.00

| Compliance | Description | Data | Compliance | Description | Data |
|---|---|---|---|---|---|
| N/A | Ramp Length (in) | 72.0 | Yes | BlendTrans Slope (%) | 1.5 |
| Yes | Ramp Width (in) | 56.0 | Yes | BlendTrans XSlope (%) | 0.6 |
| N/A | Flare Type LT | Sloped | N/A | Flare Type RT | Sloped |
| No | Flare Slope LT (%) | N/A | No | Flare Slope RT (%) | N/A |
| N/A | Flare Traversable LT? | Yes | N/A | Flare Traversable RT? | Yes |
| N/A | Landing Length (in) | N/A | Yes | DWS Provided? | Yes |
| N/A | Landing Width (in) | N/A | Yes | DWS Contrast? | Yes |
| N/A | Landing Slope (%) | N/A | Yes | DWS Length (in) | 24.0 |
| N/A | Landing X Slope (%) | N/A | Yes | DWS Full Width? | Yes |
| N/A | Landing Curb? (Y/N) | No | No | DWS Offset (in) | 4.0 |
| N/A | Shared Landing? | No | | | |
| Yes | Gutter Ponding? | No | Yes | Gutter Slope (%) | 1.1 |
| Yes | Gutter Lip Ht (in) | 0.0 | Yes | Gutter X Slope (%) | 0.3 |
| N/A | Painted X Walk1? | No | N/A | Painted X Walk2? | N/A |
| | X Walk 1 Direction | To NW | | X Walk 2 Direction | N/A |
| | X Walk 1 Width (in) | N/A | | X Walk 2 Width (in) | N/A |
| | X Walk 1 Slope (%) | 4.7 | | X Walk 2 Slope (%) | N/A |
| | X Walk 1 X Slope (%) | 2.8 | | X Walk 2 X Slope (%) | N/A |
| N/A | Ramp inside XWalk1? | N/A | N/A | Ramp inside XWalk2? | N/A |
| | Road Slope (%) | 2.8 | | Clear Space? | Yes |
| | Road X Slope (%) | 4.7 | N/A | Clear Space to XWalk (in) | N/A |
| Yes | Any Obstructions? | No | Yes | Storm Grate/Utility Hazard? | No |
| | Obstruction Type | | | Storm Grate/Utility Type | |
| | | N/A | | | N/A |
| | | | Yes | Surface Condition? (G/P) | Good |
| | | | No | Curb Slope (%) | 8.9 |