cole

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Intersection ID: 8040	Main Street: STATESVILLE_AV			treet:	ALMA_CT	Location:	NW		
ADA ID: 0063E3EF7849	Ramp Type: PerpDiag			nitial Pass/Fail: Fail Overall Compliance: No				o Severity Score:	22.5
Codes/Mitigation Info/Possible Solution				Field Measurements/Component Compliance					
	1 Martin Martin	Possible Solutions:					Compliance Description		Data
L. ATTALET S.		Remove & Replace Curb Ramp W Two New Directional Ramps or Equivalent.		N/A	Ramp Length (in)	59.5		Ramp Slope (%)	9.5
				No	Ramp Width (in)	38.0	No	Ramp XSlope (%)	4.7
				N/A	Flare Type LT	N/A		Flare Type RT	N/A
				N/A	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)	N/A
				N/A	Flare Traversable LT?	N/A	N/A	Flare Traversable RT?	N/A
				N/A	Landing Length (in)		N/A	DWS Provided?	N/A
		Surveyor Notes:		N/A	Landing Width (in)	N/A	N/A	DWS Contrast?	N/A
		N/A		N/A	Landing Slope (%)	N/A	N/A	DWS Length (in)	N/A
				N/A	Landing X Slope (%)	N/A		DWS Full Width?	N/A
				N/A	Landing Curb? (Y/N)		N/A	DWS Offset (in)	N/A
				N/A	Shared Landing?	N/A			
		PROW/ADA:		N/A	Gutter Ponding?		N/A	Gutter Slope (%)	N/A
		Not Found, R304.5.1, R304.2.2,		N/A	Gutter Lip Ht (in)	N/A		Gutter X Slope (%)	N/A
		R304.5.3		N/A	Painted X Walk1?	No		Painted X Walk2?	No
					X Walk 1 Direction	To S		X Walk 2 Direction	To E
				N/A	X Walk 1 Width (in)		N/A	X Walk 2 Width (in)	N/A
Street 1 Name	ALMA CT				X Walk 1 Slope (%)	1.5		X Walk 2 Slope (%)	0.7
Stop Condition-Street 2	StopSign				X Walk 1 X Slope (%)	0.2		X Walk 2 X Slope (%)	4.5
Street 2 Name	STATESVILLE AV			N/A	Ramp inside XWalk1?	N/A	N/A	Ramp inside XWalk2?	N/A
Stop Condition-Street 1	None				Road Slope (%)	4.5		Clear Space?	N/A
					Road X Slope (%)	3.4	N/A	Clear Space to XWalk (in)	N/A
				N/A	Any Obstructions?		N/A	Storm Grate/Utility Hazard?	N/A
		Total Cost: \$ 32	200.00		Obstruction Type			Storm Grate/Utility Type	
		····· • ••				N/A			N/A

es Surface Condition? (G/P)

Good

