

## **Access Compliance Report Public Rights-of-Way** (Curb Ramps)



Data

13.5

Intersection ID: 27355 Main Street: JOHNSTON RD **Cross Street: BRIXHAM AV** Location: NW **Overall Compliance: No ADA ID: 0098E61B7CEA** Ramp Type: Perp Initial Pass/Fail: Fail Severity Score: 26.25

**Codes/Mitigation Info/Possible Solution** 

## Field Measurements/Component Compliance


No

Compliance Description

Ramp Slope (%)

Data

47.0



**BRIXHAM MLL AV** Street 1 Name Stop Condition-Street 2 Signal N/A Street 2 Name Stop Condition-Street 1 N/A

Possible Solutions:	Compl	iance	Description
Remove & Replace Entire Ramp.	N/A	Ram	p Length (in)
·	Yes	Ram	p Width (in)
	N/A	Flare	Type LT
	N/A	Flare	Slope LT (%)
	N/A	Flare	Traversable L
	N/A	Land	ing Length (in)
Surveyor Notes:	N/A	Land	ing Width (in)
N/A	N/A	Land	ing Slope (%)
	N/A	Land	ing X Slope (%
	N/A	Land	ing Curb? (Y/N
	N/A	Shar	ed Landing?
PROW/ADA:	N/A	Gutte	er Ponding?
Not Found, R304.2.2, R304.5.3	N/A	Gutte	er Lip Ht (in)
	N/A	Paint	ed X Walk1?
		X Wa	alk 1 Direction
	N/A	X Wa	alk 1 Width (in)
		X Wa	alk 1 Slope (%)
		X Wa	alk 1 X Slope (%
	N/A	Ram	p inside XWalk′
		Poor	Slone (%)

	PRITTAL HILL
-	719 nr/2 (213 213)

Total Cost:



