

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Intersection ID: 3688 Main Street: CINNABAY DR **Cross Street: TREYBURN DR** Location: SE ADA ID: 0133142164B9 Ramp Type: BlendTrans2 Initial Pass/Fail: Fail **Overall Compliance: No Severity Score:** 12.5

Codes/Mitigation Info/Possible Solution

Field Measurements/Component Compliance



TREYBURN DR Street 1 Name Stop Condition-Street 1 None Street 2 Name N/A Stop Condition-Street 2 N/A

1 033IDIC OCIULIOII				
Possible Solutions:	<u>c</u>			
Remove & Replace Curb Ramp With	N			
Two New Directional Ramps or	Υ			
Equivalent.				
	N			
	N			
	N			
Surveyor Notes:	N			
GTR GAP 1.0, NO LT SW				
·	N			
	N			
	N			
PROW/ADA:	N			
Not Found, R304.5.3				
	N			



Total Cost:



3200.00

Comp	liance Description	Data	Comp	liance Description	Data
N/A	Ramp Length (in)	91.0	Yes	BlendTrans Slope (%)	1.9
Yes	Ramp Width (in)	48.0	No	BlendTrans XSlope (%)	6.1
N/A	Flare Type LT	N/A	N/A	Flare Type RT	N/A
N/A	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)	N/A
N/A	Flare Traversable LT?	N/A	N/A	Flare Traversable RT?	N/A
N/A	Landing Length (in)	N/A	N/A	DWS Provided?	N/A
N/A	Landing Width (in)	N/A	N/A	DWS Contrast?	N/A
N/A	Landing Slope (%)	N/A	N/A	DWS Length (in)	N/A
N/A	Landing X Slope (%)	N/A	N/A	DWS Full Width?	N/A
N/A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset (in)	N/A
N/A	Shared Landing?	N/A			
N/A	Gutter Ponding?	N/A	N/A	Gutter Slope (%)	N/A
N/A	Gutter Lip Ht (in)	N/A	N/A	Gutter X Slope (%)	N/A
N/A	Painted X Walk1?	No	N/A	Painted X Walk2?	N/A
	X Walk 1 Direction	To N		X Walk 2 Direction	N/A
	X Walk 1 Width (in)	N/A		X Walk 2 Width (in)	N/A
	X Walk 1 Slope (%)	1.3		X Walk 2 Slope (%)	N/A
	X Walk 1 X Slope (%)	6.9		X Walk 2 X Slope (%)	N/A
N/A	Ramp inside XWalk1?	N/A	N/A	Ramp inside XWalk2?	N/A
	Road Slope (%)	6.9		Clear Space?	N/A
	Road X Slope (%)	1.3	N/A	Clear Space to XWalk (in)	N/A
N/A	Any Obstructions?	N/A	N/A	Storm Grate/Utility Hazard?	N/A
	Obstruction Type			Storm Grate/Utility Type	
		N/A	l		N/A
			Yes	Surface Condition? (G/P)	Good
19 MO 1	The state of the s		No	Curb Slope (%)	10.2