

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Data

7.0

1.3

N/A

No

To E

N/A

1.4

0.9

N/A

N/A

N/A

N/A

N/A

Good

Intersection ID: 13159 Main Street: CENTRAL_AV Cross Street: NANDINA_ST Location: SW

ADA ID: 017A02D67D0C Ramp Type: PerpDiag Initial Pass/Fail: Fail Overall Compliance: No Severity Score: 8.75

Codes/Mitigation Info/Possible Solution

Field Measurements/Component Compliance

Yes

Yes

N/A

Yes

Compliance Description

Ramp Slope (%)

Flare Type RT

Ramp XSlope (%)

Flare Slope RT (%)

DWS Provided?

DWS Contrast?

DWS Length (in)

DWS Full Width?

DWS Offset (in)

Gutter Slope (%)

Gutter X Slope (%)

Painted X Walk2?

X Walk 2 Direction

X Walk 2 Width (in)

X Walk 2 Slope (%)

X Walk 2 X Slope (%)

Ramp inside XWalk2?

Clear Space to XWalk (in)

Storm Grate/Utility Type

Surface Condition? (G/P)

Storm Grate/Utility Hazard?

Clear Space?

Flare Traversable RT?

Data

58.0

45.0

N/A

No

To N

N/A

0.8

0.6

N/A

2.2

0.1

N/A

N/A



Street 1 Name CENTRAL AV
Stop Condition-Street 2 StopSign
Street 2 Name NANDINA ST
Stop Condition-Street 1 None

Possible Solutions: Compliance Description N/A Ramp Length (in) Remove & Replace Curb Ramp With Two New Directional Ramps or No Ramp Width (in) Equivalent. N/A Flare Type LT N/A Flare Slope LT (%) N/A Flare Traversable LT? N/A Landing Length (in) Surveyor Notes: N/A Landing Width (in) N/A N/A Landing Slope (%) N/A Landing X Slope (%) N/A Landing Curb? (Y/N) N/A Shared Landing? PROW/ADA: N/A **Gutter Ponding?** Not Found, R304.5.1 N/A Gutter Lip Ht (in) N/A Painted X Walk1? X Walk 1 Direction N/A X Walk 1 Width (in) X Walk 1 Slope (%) X Walk 1 X Slope (%) N/A Ramp inside XWalk1? Road Slope (%) Road X Slope (%)





Total Cost:



N/A

3200.00

Any Obstructions?

Obstruction Type