

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Yes

Surface Condition? (G/P)

Good

Intersection ID: 15531	1 Main Street: AMITY SPRINGS DR			Cross Street: N_SHARON_AMITY_RD				Location:	SE
ADA ID: 02DB6647B235				Initial Pass/Fail: Fail Overall Compliance:					12.5
Codes/Mitigation Info/Possible Solution				Field Measurements/Component Compliance					
Possible Solutions:									Data
PAGE (K)		Remove & Replace Entire Ram) .	N/A	Ramp Length (in)	58.0	No	Ramp Slope (%)	11.4
	Sec. The way			Yes	Ramp Width (in)	48.0	Yes	Ramp XSlope (%)	0.8
				N/A	Flare Type LT	N/A	N/A	Flare Type RT	N/A
	and the second second			N/A	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)	N/A
	Ten			N/A	Flare Traversable LT?	N/A	N/A	Flare Traversable RT?	N/A
AMITY_SPRIN	ICS DR	-		N/A	Landing Length (in)	N/A	N/A	DWS Provided?	N/A
	The star	Surveyor Notes:		N/A	Landing Width (in)	N/A	N/A	DWS Contrast?	N/A
		N/A		N/A	Landing Slope (%)	N/A	N/A	DWS Length (in)	N/A
	A Marth			N/A	Landing X Slope (%)	N/A	N/A	DWS Full Width?	N/A
2	2100 1990 - C			N/A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset (in)	N/A
	The state			N/A	Shared Landing?	N/A			
	A.F. Car	PROW/ADA:		N/A	Gutter Ponding?	N/A	N/A	Gutter Slope (%)	N/A
	and the	Not Found, R304.2.2		N/A	Gutter Lip Ht (in)	N/A	N/A	Gutter X Slope (%)	N/A
	A Start St	·····		N/A	Painted X Walk1?	No	N/A	Painted X Walk2?	N/A
	and the second				X Walk 1 Direction	To N		X Walk 2 Direction	N/A
				N/A	X Walk 1 Width (in)	N/A	N/A	X Walk 2 Width (in)	N/A
Street 1 Name AMITY	SPRINGS DR	_			X Walk 1 Slope (%)	2.2		X Walk 2 Slope (%)	N/A
Stop Condition-Street 2	StopSign				X Walk 1 X Slope (%)	0.2		X Walk 2 X Slope (%)	N/A
Street 2 Name	N/A			N/A	Ramp inside XWalk1?	N/A	N/A	Ramp inside XWalk2?	N/A
Stop Condition-Street 1	N/A				Road Slope (%)	N/A	N/A	Clear Space?	N/A
					Road X Slope (%)	N/A	N/A	Clear Space to XWalk (in)	N/A
				N/A	Any Obstructions?	N/A	N/A	Storm Grate/Utility Hazard?	N/A
		Total Cost: \$	1850.00		Obstruction Type			Storm Grate/Utility Type	
						N/A			N/A

