

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Intersection ID: 30542 Main Street: AMBERWOOD_CT Cross Street: SUMMERHILL_RIDGE_DR Location: N

ADA ID: 055BF0ADEEDF Ramp Type: PerpDiag Initial Pass/Fail: Fail Overall Compliance: No Severity Score: 12.5

Codes/Mitigation Info/Possible Solution

Field Measurements/Component Compliance



Street 1 Name
Stop Condition-Street 2
Street 2 Name
Stop Condition-Street 1

AMBERWOOD CT
StopSign
SUMMERHILL RIDGE DR
None

Possible Solutions:

Remove & Replace Curb Ramp With
Two New Directional Ramps or
Equivalent.

Surveyor Notes:
N/A

PROW/ADA:
Not Found, R304.5.3

Total Cost: \$ 3200.00

| Field Measurements/Component Compliance | | | | | | |
|---|------------------------|-----------------------|-------|------------------------|-----------------------------|-------|
| | Compliance Description | | Data | Compliance Description | | Data |
| | N/A | Ramp Length (in) | 50.0 | Yes | Ramp Slope (%) | 6.4 |
| | Yes | Ramp Width (in) | 54.0 | No | Ramp XSlope (%) | 5.4 |
| | N/A | Flare Type LT | N/A | N/A | Flare Type RT | N/A |
| | N/A | Flare Slope LT (%) | N/A | N/A | Flare Slope RT (%) | N/A |
| | N/A | Flare Traversable LT? | N/A | N/A | Flare Traversable RT? | N/A |
| | N/A | Landing Length (in) | N/A | N/A | DWS Provided? | N/A |
| | N/A | Landing Width (in) | N/A | N/A | DWS Contrast? | N/A |
| | N/A | Landing Slope (%) | N/A | N/A | DWS Length (in) | N/A |
| | N/A | Landing X Slope (%) | N/A | N/A | DWS Full Width? | N/A |
| | N/A | Landing Curb? (Y/N) | N/A | N/A | DWS Offset (in) | N/A |
| | N/A | Shared Landing? | N/A | | | |
| | N/A | Gutter Ponding? | N/A | N/A | Gutter Slope (%) | N/A |
| | N/A | Gutter Lip Ht (in) | N/A | N/A | Gutter X Slope (%) | N/A |
| | N/A | Painted X Walk1? | No | N/A | Painted X Walk2? | No |
| | | X Walk 1 Direction | To SW | | X Walk 2 Direction | To SE |
| | N/A | X Walk 1 Width (in) | N/A | N/A | X Walk 2 Width (in) | N/A |
| | | X Walk 1 Slope (%) | 1.8 | | X Walk 2 Slope (%) | 5.7 |
| | | X Walk 1 X Slope (%) | 4.6 | | X Walk 2 X Slope (%) | 0.6 |
| | N/A | Ramp inside XWalk1? | N/A | N/A | Ramp inside XWalk2? | N/A |
| | | Road Slope (%) | 4.1 | N/A | Clear Space? | N/A |
| | | Road X Slope (%) | 4.4 | N/A | Clear Space to XWalk (in) | N/A |
| | N/A | Any Obstructions? | N/A | N/A | Storm Grate/Utility Hazard? | N/A |
| | | Obstruction Type | | | Storm Grate/Utility Type | |
| | | | N/A | | | N/A |
| | | | | Yes | Surface Condition? (G/P) | Good |
| 200 | The second | | | | | |





