


Access Compliance Report

Public Rights-of-Way

(Curb Ramps)

| | | | |
|---|-------------------------|---|------------------------|
| Intersection ID: 10040201 | Main Street: TYVOLA_RD | Cross Street: N/A | Location: SE |
| ADA ID: 055CCA79D7C2 | Ramp Type: Directional1 | Initial Pass/Fail: Fail | Overall Compliance: No |
| Severity Score: 1.25 | | | |
| Codes/Mitigation Info/Possible Solution | | Field Measurements/Component Compliance | |

| | | | | | | | |
|--|-------------------------------|------------|-----------------------|------|------------|-----------------------------|------|
|  | Possible Solutions: | | | | | | |
| | Remove & Replace Entire Ramp. | | | | | | |
| | Surveyor Notes: N/A | Compliance | Description | Data | Compliance | Description | Data |
| | | N/A | Ramp Length (in) | 95.0 | N/A | Grade Break? | N/A |
| | | Yes | Ramp Width (in) | 67.0 | N/A | Grade Break Slope (%) | 0.0 |
| | | Yes | Ramp Slope (%) | 6.3 | N/A | Grade Break XSlope (%) | 0.0 |
| | | No | Ramp XSlope (%) | 5.0 | | | |
| | | N/A | Flare Type LT | N/A | N/A | Flare Type RT | N/A |
| | | N/A | Flare Slope LT (%) | N/A | N/A | Flare Slope RT (%) | 0.0 |
| | | N/A | Flare Traversable LT? | N/A | N/A | Flare Traversable RT? | N/A |
| | | N/A | Landing Length (in) | 0.0 | N/A | DWS Provided? | N/A |
| | | N/A | Landing Width (in) | 0.0 | N/A | DWS Contrast? | N/A |
| | PROW/ADA: R304.5.3 | N/A | Landing Slope (%) | 0.0 | N/A | DWS Length (in) | N/A |
| | | N/A | Landing X Slope (%) | 0.0 | N/A | DWS Full Width? | N/A |
| | | N/A | Landing Curb? (Y/N) | N/A | N/A | DWS Offset LT (in) | N/A |
| | | N/A | Shared Landing? | N/A | N/A | DWS Offset RT (in) | N/A |
| | | N/A | Gutter Ponding? | 0.0 | N/A | Gutter Slope (%) | N/A |
| | | N/A | Gutter Lip Ht (in) | 0.0 | N/A | Gutter X Slope (%) | N/A |
| | | N/A | Painted X Walk1? | No | | Road Slope (%) | 0.3 |
| | | | X Walk 1 Direction | To W | | Road X Slope (%) | 0.5 |
| | | | X Walk 1 Width (in) | N/A | | Clear Space? | N/A |
| | | | X Walk 1 Slope (%) | 0.3 | N/A | Clear Space to XWalk (in) | N/A |
| | | | X Walk 1 X Slope (%) | 0.5 | N/A | Storm Grate/Utility Hazard? | N/A |
| | | N/A | Ramp inside XWalk1? | N/A | | Storm Grate/Utility Type | |
| | | N/A | Any Obstructions? | N/A | | | N/A |
| | | | Obstruction Type | | Yes | Surface Condition? (G/P) | Good |
| | | | | | N/A | Curb Slope (%) | 12.9 |
| | Total Cost: | \$ | 1600.00 | | | | |

