

Access Compliance Report Public Rights-of-Way (Curb Ramps)



		```		•	-/						
Intersection ID: 29786 Main Street: ELM_LN			Cross	Cross Street: MILLWRIGHT_LN				Location: NE			
ADA ID: 060C71678081	Ramp Type: Combination1Diag		Initial I	Initial Pass/Fail: Fail Overall Complian			nce: No Severity Score: 0		0		
Codes/Mitigation Info/Possible Solution					Field Measurements/Component Compliance						
	Poss	Possible Solutions:			Compliance Description		Data	Data Compliance Description		Data	
	Re	Remove & Replace Curb Ramp Wi Two New Directional Ramps or Equivalent.		With	N/A	Ramp Length LT (in)	40.5	N/A	Ramp Length RT (in)	47.0	
	Ти				Yes	Ramp Width LT (in)	48.0	Yes	Ramp Width RT (in)	48.0	
	Ec				Yes	Ramp Slope LT (%)	5.9	Yes	Ramp Slope RT (%)	1.4	
					Yes	Ramp XSlope LT (%	0.5	Yes	Ramp XSlope RT (%)	0.9	
and the second					N/A	Ramp Length (in)	73.0	Yes	Ramp Slope (%)	5.3	
	and a state of the				Yes	Ramp Width (in)	65.0	No	Ramp XSlope (%)	5.2	
3	Surv	eyor Notes:			N/A	Flare Type LT	N/A	N/A	Flare Type RT	N/A	
	R	RT RP < 5%			N/A	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)	N/A	
<b>MILLWRICHT</b>		<u>v</u>			N/A	Flare Traversable LT	? <b>N/A</b>	N/A	Flare Traversable RT?	N/A	
	<u>LIN</u>				N/A	Landing Length (in)	N/A	N/A	DWS Provided?	N/A	
C. S. B. L.					N/A	Landing Width (in)	N/A	N/A	DWS Contrast?	N/A	
	E PRC	)W/ADA:			N/A	Landing Slope (%)	N/A	N/A	DWS Length (in)	N/A	
	R3	R304.5.3			N/A	Landing X Slope (%)	N/A	N/A	DWS Full Width?	N/A	
					N/A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset (in)	N/A	
					N/A	Shared Landing?	N/A				
					N/A	Gutter Ponding?	N/A	N/A	Gutter Slope (%)	N/A	
Street 1 Name	None				N/A	Gutter Lip Ht (in)	N/A	N/A	Gutter X Slope (%)	N/A	
Stop Condition-Street 1	ELM LN				N/A	Painted X Walk1?	No	N/A	Painted X Walk2?	No	
Street 2 Name	StopSign					X Walk 1 Direction	To NW		X Walk 2 Direction	To SW	
Stop Condition-Street 2 MILLW	RIGHT LN					X Walk 1 Width (in)	N/A		X Walk 2 Width (in)	N/A	
						X Walk 1 Slope (%)	3.9		X Walk 2 Slope (%)	2.6	
						X Walk 1 X Slope (%	) 0.2		X Walk 2 X Slope (%)	1.6	
	Tota	l Cost:	\$	3200.00	N/A	Ramp inside XWalk1	? <b>N/A</b>	N/A	Ramp inside XWalk2?	N/A	
						Road Slope (%)	0.9		Clear Space?	N/A	
						Road X Slope (%)	2.2	N/A	Clear Space to XWalk (in)	N/A	
En al	Milwright		1	×.	Milwri	oht al		N/A	Any Obstruction?	N/A	
							Obstruction Type				
					Arrent	A CONTRACTOR				N/A	
	1200				- Section			N/A	Storm Grate/Utility Hazard?	N/A	
									Storm Grate/Utility Type	17/4	
		- +	And an and a second			and the second s				N/A	

Yes	Surface Condition? (G/P)	Good
	Curb Slope (%)	0.2