cole

Access Compliance Report Public Rights-of-Way (Curb Ramps)



N/A

Curb Slope (%)

2.6

Intersection ID: 12950	Main Street: MORRIS_FIELD_DR			Cross Street: SEYMOUR_DR				Location:	SE
ADA ID: 06C3A6792AA9	Ramp Type: ParaDiag			nitial Pass/Fail: Fail Overall Compliance: No				o Severity Score:	13.75
Codes/Mitigation Info/Possible Solution				Field Measurements/Component Compliance					
		Possible Solutions:		Compliance Description Data			Compliance Description Data		
		Remove & Replace Curb Ra	amp With	N/A	Ramp Length LT (in)	59.0	N/A	Ramp Length RT (in)	52.0
		Two New Directional Ramp		Yes	Ramp Width LT (in)	73.0	Yes	Ramp Width RT (in)	72.0
		Equivalent.		No	Ramp Slope LT (%)	9.7	Yes	Ramp Slope RT (%)	2.0
				Yes	Ramp XSlope LT (%)	1.4	No	Ramp XSlope RT (%)	3.5
3				N/A	Landing Length (in)	N/A	N/A	DWS Provided?	N/A
	Server Land			N/A	Landing Width (in)	N/A	N/A	DWS Contrast?	N/A
5. ST	MOUR_DR	Surveyor Notes:		N/A	Landing Slope (%)	N/A	N/A	DWS Length (in)	N/A
		RT RP < 5%		N/A	Landing X Slope (%)	N/A	N/A	DWS Full Width?	N/A
	A DE THEN			N/A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset (in)	N/A
				N/A	Shared Landing?	N/A			
	A Markey			N/A	Gutter Ponding?	N/A	N/A	Gutter Slope (%)	N/A
		PROW/ADA:		N/A	Gutter Lip Ht (in)	N/A	N/A	Gutter X Slope (%)	N/A
		R304.3.2, R304.5.3		N/A	Painted X Walk1?	No	N/A	Painted X Walk2?	No
					X Walk 1 Direction	To NE		X Walk 2 Direction	To NW
				N/A	X Walk 1 Width (in)	N/A	N/A	X Walk 2 Width (in)	N/A
					X Walk 1 Slope (%)	2.0		X Walk 2 Slope (%)	4.5
Street 1 Name	SEYMOUR DR	-			X Walk 1 X Slope (%)	4.4		X Walk 2 X Slope (%)	1.8
Stop Condition-Street 1	StopSign			N/A	Ramp inside XWalk1?	N/A	N/A	Ramp inside XWalk2?	N/A
Street 2 Name	MORRISFIELD DR				Road Slope (%)	2.9	N/A	Clear Space?	N/A
Stop Condition-Street 2	None				Road X Slope (%)	2.5	N/A	Clear Space to XWalk (in)	N/A
				N/A	Any Obstructions?		N/A	Storm Grate/Utility Hazard?	N/A
					Obstruction Type			Storm Grate/Utility Type	
		Total Cost: \$	3200.00			N/A			N/A
							Yes	Surface Condition? (G/P)	Good

