cole

Access Compliance Report Public Rights-of-Way (Curb Ramps)



N/A

Curb Slope (%)

N/A

Intersection ID: 5294	tersection ID: 52944 Main Street: CAMBRIDGE_COMMONS_DR Cross							Location:	NW
ADA ID: 0A177999A	6C9 Ramp Type: Para			Initial Pass/Fail: Fail Overall Compliance: No				o Severity Score:	25
Codes/Mitigation Info/Possible Solution				Field Measurements/Component Compliance					
HH.		Possible Solutions:		Compliance Description			ata Compliance Description		Data
- H	german AR	Remove & Replace Entire Ra	mp.	N/A	Ramp Length LT (in)	69.0	N/A	Ramp Length RT (in)	67.5
the second second				Yes	Ramp Width LT (in)	85.0	Yes	Ramp Width RT (in)	85.0
And Inches and		(Yes	Ramp Slope LT (%)	0.2	No	Ramp Slope RT (%)	12.8
		1		Yes	Ramp XSlope LT (%)	0.1	Yes	Ramp XSlope RT (%)	0.0
The second second				N/A	Landing Length (in)	N/A	N/A	DWS Provided?	N/A
· · · · · · · · · · · · · · · · · · ·	Carlos VI / -			N/A	Landing Width (in)	N/A	N/A	DWS Contrast?	N/A
CAMP	A PERION	Surveyor Notes:		N/A	Landing Slope (%)	N/A	N/A	DWS Length (in)	N/A
EDGINE CON		LT RP < 5%		N/A	Landing X Slope (%)	N/A	N/A	DWS Full Width?	N/A
	ONO -			N/A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset (in)	N/A
C. SALVEST	THER E			N/A	Shared Landing?	N/A			
de la calenda				N/A	Gutter Ponding?	N/A	N/A	Gutter Slope (%)	N/A
		PROW/ADA:		N/A	Gutter Lip Ht (in)	N/A	N/A	Gutter X Slope (%)	N/A
A State of the second sec		R304.3.2		N/A	Painted X Walk1?	No	N/A	Painted X Walk2?	N/A
NEXC AND					X Walk 1 Direction	To S		X Walk 2 Direction	N/A
				N/A	X Walk 1 Width (in)	N/A	N/A	X Walk 2 Width (in)	N/A
					X Walk 1 Slope (%)	0.7		X Walk 2 Slope (%)	N/A
Street 1 Name	CAMBRIDGE COMMONS DR				X Walk 1 X Slope (%)	6.2		X Walk 2 X Slope (%)	N/A
Stop Condition-Street 1	None			N/A	Ramp inside XWalk1?	N/A	N/A	Ramp inside XWalk2?	N/A
Street 2 Name	N/A				Road Slope (%)	N/A	N/A	Clear Space?	N/A
Stop Condition-Street 2	N/A				Road X Slope (%)	N/A	N/A	Clear Space to XWalk (in)	N/A
				N/A	Any Obstructions?	N/A	N/A	Storm Grate/Utility Hazard?	N/A
					Obstruction Type			Storm Grate/Utility Type	
		Total Cost: \$	1600.00			N/A			N/A
							Yes	Surface Condition? (G/P)	Good

