

## Access Compliance Report Public Rights-of-Way (Curb Ramps)



Data

51.0

49.0

3.5

4.4

11.9

4.8

N/A

No

N/A

0.9

0.3

N/A

N/A

N/A

N/A

N/A

N/A

N/A

5.5

Good

To NE

Intersection ID: 27733 Main Street: LANCASTER\_HY Cross Street: SOUTHCREST\_LN Location: NW

ADA ID: 0AE98EFD8EC1 Ramp Type: Combination1Diag Initial Pass/Fail: Fail Overall Compliance: No Severity Score: 0

Codes/Mitigation Info/Possible Solution

## Field Measurements/Component Compliance

N/A

N/A

N/A

N/A

Yes

Ramp inside XWalk2?

Clear Space to XWalk (in)

Storm Grate/Utility Hazard?

Storm Grate/Utility Type

Surface Condition? (G/P)

Clear Space?

Any Obstruction?

**Obstruction Type** 

Curb Slope (%)

N/A

3.9

1.1



Street 1 Name
Stop Condition-Street 1
Street 2 Name
Stop Condition-Street 2

StopSign SOUTHCREST LN None LANCASTER HY Possible Solutions:

Remove & Replace Curb Ramp With Two New Directional Ramps or Equivalent.

Surveyor Notes:

RT RP < 5%

PROW/ADA:

Not Found, R304.5.1, R304.2.2, R304.5.3

Total Cost:









N/A

Ramp inside XWalk1?

Road Slope (%)

3200.00