cole

Access Compliance Report Public Rights-of-Way (Curb Ramps)



| Intersection ID: 10018468 | Main Street: POSSUM_TROT_LN | | | Cross Street: N/A | | | | Location: | S |
|---|-----------------------------|----------------------------|---------|--|-----------------------|-------|----------------------------|-----------------------------|------|
| ADA ID: 0B33AF76F001 | Ramp Type: Perp | | | Initial Pass/Fail: Fail Overall Compliance | | | nce: N | o Severity Score: | 8.75 |
| Codes/Mitigation Info/Possible Solution | | | | Field Measurements/Component Compliance | | | | | |
| | | Possible Solutions: | | Compliance Description Data | | | Compliance Description Dat | | Data |
| | | Remove & Replace Entire Ra | mp. | N/A | Ramp Length (in) | 46.0 | Yes | Ramp Slope (%) | 6.9 |
| | | - | • | No | Ramp Width (in) | 45.5 | Yes | Ramp XSlope (%) | 2.0 |
| The Artest | st 1 | | | N/A | Flare Type LT | N/A | N/A | Flare Type RT | N/A |
| | 7 | | | N/A | Flare Slope LT (%) | N/A | N/A | Flare Slope RT (%) | N/A |
| have the state of | | | | N/A | Flare Traversable LT? | N/A | N/A | Flare Traversable RT? | N/A |
| | ALL DE | | | N/A | Landing Length (in) | N/A | N/A | DWS Provided? | N/A |
| | The second of | Surveyor Notes: | | N/A | Landing Width (in) | N/A | N/A | DWS Contrast? | N/A |
| | a de pro | N/A | | N/A | Landing Slope (%) | N/A | N/A | DWS Length (in) | N/A |
| A CONTRACT OF | | | | N/A | Landing X Slope (%) | N/A | N/A | DWS Full Width? | N/A |
| | A | ÷ | | N/A | Landing Curb? (Y/N) | N/A | N/A | DWS Offset (in) | N/A |
| | | | | N/A | Shared Landing? | N/A | | | |
| | ANK | PROW/ADA: | | N/A | Gutter Ponding? | N/A | N/A | Gutter Slope (%) | N/A |
| | A BAR | Not Found, R304.5.1 | | N/A | Gutter Lip Ht (in) | N/A | N/A | Gutter X Slope (%) | N/A |
| 5 / E UNION | | | | N/A | Painted X Walk1? | No | N/A | Painted X Walk2? | N/A |
| A A A A A A A A A A A A A A A A A A A | | | | | X Walk 1 Direction | To NW | | X Walk 2 Direction | N/A |
| | and a second second | | | N/A | X Walk 1 Width (in) | N/A | N/A | X Walk 2 Width (in) | N/A |
| Street 1 Name PO | OSSUM TROT LN | - | | | X Walk 1 Slope (%) | 0.6 | | X Walk 2 Slope (%) | N/A |
| Stop Condition-Street 2 | None | | | | X Walk 1 X Slope (%) | 4.1 | | X Walk 2 X Slope (%) | N/A |
| Street 2 Name | N/A | | | N/A | Ramp inside XWalk1? | N/A | N/A | Ramp inside XWalk2? | N/A |
| Stop Condition-Street 1 | N/A | | | | Road Slope (%) | N/A | N/A | Clear Space? | N/A |
| | | | | | Road X Slope (%) | N/A | N/A | Clear Space to XWalk (in) | N/A |
| | | | | N/A | Any Obstructions? | N/A | N/A | Storm Grate/Utility Hazard? | N/A |
| | | Total Cost: \$ | 1850.00 |) | Obstruction Type | | | Storm Grate/Utility Type | |
| | | | | | | N/A | | | N/A |

Yes Surface Condition? (G/P)

Good

