

ADA ID: 0BC0A25C41AF

Access Compliance Report Public Rights-of-Way (Curb Ramps)



2.5

Data

4.3

0.9

None

N/A

N/A

Yes

Severity Score:

Compliance Description

Flare Type RT

Flare Slope RT (%)

DWS Provided?

Flare Traversable RT?

BlendTrans Slope (%)

BlendTrans XSlope (%)

Intersection ID: 10015853 Main Street: STATESVILLE_AV Cross Street: N/A Location: E

Initial Pass/Fail: Pass

N/A

Yes

N/A

N/A

N/A

Yes

Compliance Description

Ramp Length (in)

Ramp Width (in)

Flare Slope LT (%)

Landing Length (in)

Flare Traversable LT?

Flare Type LT

Codes/Mitigation Info/Possible Solution

Ramp Type: BlendTrans1

Field Measurements/Component Compliance

Yes

Yes

N/A

N/A

N/A

Yes

Data

71.0

60.0

None

N/A

N/A

59.5

Overall Compliance: No



Street 1 Name
Stop Condition-Street 1
None
Street 2 Name
N/A
Stop Condition-Street 2
N/A

Possible Solutions:

Remove & Replace Curb Ramp With Two New Directional Ramps or Equivalent.

Surveyor Notes:

NO CURB LINE, DWS OS MEASURED TO ASP

PROW/ADA:

R304.2.2-Perp, R304.3.2-Para, R305.1.4, R305.2

Total Cost: \$ 3200.00

Yes Landing Width (in) 60.0 Yes **DWS Contrast?** Yes 2.3 Yes No Landing Slope (%) DWS Length (in) 24.0 Yes Landing X Slope (%) 0.6 No DWS Full Width? No N/A Landing Curb? (Y/N) No No DWS Offset (in) 7.0 N/A Shared Landing? No Yes **Gutter Ponding?** No Yes Gutter Slope (%) 3.0 Yes Gutter Lip Ht (in) 0.0 Yes Gutter X Slope (%) 0.2 N/A Painted X Walk1? No N/A Painted X Walk2? N/A X Walk 1 Direction To W X Walk 2 Direction N/A N/A X Walk 2 Width (in) X Walk 1 Width (in) N/A X Walk 1 Slope (%) 4.5 X Walk 2 Slope (%) N/A X Walk 1 X Slope (%) 0.3 X Walk 2 X Slope (%) N/A N/A N/A Ramp inside XWalk2? N/A N/A Ramp inside XWalk1? Road Slope (%) 0.3 Clear Space? Yes N/A Road X Slope (%) 4.5 Clear Space to XWalk (in) N/A Yes Any Obstructions? No Yes Storm Grate/Utility Hazard? No **Obstruction Type** Storm Grate/Utility Type N/A N/A Yes Surface Condition? (G/P) Good N/A Curb Slope (%) N/A



