## cole

## Access Compliance Report Public Rights-of-Way (Curb Ramps)



| · · · ·   |               |   |              |   |           |                        |                             |       |
|---|---------------|---|--------------|---|-----------|------------------------|-----------------------------|-------|
| Intersection ID: 10035061   | Main Str      | eet: PROVIDENCE_RD                      | Cross Stre   | et: N/A                                     | Location: | NW                     |                             |       |
| ADA ID: 0BE84795A209  | Ramp Ty       | ype: PerpDiag                           | Initial Pass | tial Pass/Fail: Fail Overall Compliance: No |           |                        | o Severity Score:           | 8.75  |
| Codes   |               | Field Measurements/Component Compliance |              |   |           |                        |                             |       |
|   |               | Possible Solutions:                     |              |   |           | Compliance Description |                             | Data  |
|   | the state     | Remove & Replace Curb Ramp W            | /ith N/A     | Ramp Length (in)                            | 54.0      | Yes                    | Ramp Slope (%)              | 5.4   |
|   |               | Two New Directional Ramps or            | No           | Ramp Width (in)                             | 46.0      | Yes                    | Ramp XSlope (%)             | 0.2   |
|   |               | Equivalent.                             | N/A          | Flare Type LT                               | N/A       | N/A                    | Flare Type RT               | N/A   |
|   |               |   | N/A          | Flare Slope LT (%)                          | N/A       | N/A                    | Flare Slope RT (%)          | N/A   |
|   |               |   | N/A          | Flare Traversable LT?                       | N/A       | N/A                    | Flare Traversable RT?       | N/A   |
|   |               |   | N/A          | Landing Length (in)                         | N/A       | N/A                    | DWS Provided?               | N/A   |
|   |               | Surveyor Notes:                         | N/A          |   | N/A       | N/A                    | DWS Contrast?               | N/A   |
| the second se |               | N/A                                     | N/A          | Landing Slope (%)                           | N/A       | N/A                    | DWS Length (in)             | N/A   |
|   | the the       |   | N/A          | Landing X Slope (%)                         | N/A       | N/A                    | DWS Full Width?             | N/A   |
| the second second   | B . CA        |   |              | Landing Curb? (Y/N)                         | N/A       | N/A                    | DWS Offset (in)             | N/A   |
|   | ×1 530        |   | N/A          | Shared Landing?                             | N/A       |                        |                             |       |
|   |               | PROW/ADA:                               | N/A          | Gutter Ponding?                             | N/A       | N/A                    | Gutter Slope (%)            | N/A   |
|   |               | Not Found, R304.5.1                     | N/A          | Gutter Lip Ht (in)                          | N/A       | N/A                    | Gutter X Slope (%)          | N/A   |
|   |               |   | N/A          | Painted X Walk1?                            | No        | N/A                    | Painted X Walk2?            | No    |
| a   |               |   |              | X Walk 1 Direction                          | To SE     |                        | X Walk 2 Direction          | To NE |
|   |               | 2                                       | N/A          | X Walk 1 Width (in)                         | N/A       | N/A                    | X Walk 2 Width (in)         | N/A   |
| Street 1 Name   | ENTRANCE      | -                                       |              | X Walk 1 Slope (%)                          | 0.9       |                        | X Walk 2 Slope (%)          | 0.2   |
| Stop Condition-Street 2   | StopSign      |   |              | X Walk 1 X Slope (%)                        | 1.6       |                        | X Walk 2 X Slope (%)        | 1.3   |
| Street 2 Name   | PROVIDENCE RD |   | N/A          | Ramp inside XWalk1?                         | N/A       | N/A                    | Ramp inside XWalk2?         | N/A   |
| Stop Condition-Street 1   | None          |   |              | Road Slope (%)                              | 1.8       | N/A                    | Clear Space?                | N/A   |
|   |               |   |              | Road X Slope (%)                            | 1.2       | N/A                    | Clear Space to XWalk (in)   | N/A   |
|   |               |   | N/#          | Any Obstructions?                           | N/A       | N/A                    | Storm Grate/Utility Hazard? | N/A   |
|   |               | Total Cost: \$ 32                       | 200.00       | Obstruction Type                            |           |                        | Storm Grate/Utility Type    |       |
|   |               |   |              |   | N/A       |                        |                             | N/A   |
|   |               |   |              |   |           | Yes                    | Surface Condition? (G/P)    | Good  |



