

## Access Compliance Report Public Rights-of-Way (Curb Ramps)



Intersection ID: 23654Main Street: COLONY\_RDCross Street: SHERWOOD\_FOREST\_DRLocation:NWADA ID: 0C548202157BRamp Type: ParaDiagInitial Pass/Fail: FailOverall Compliance: NoSeverity Score:12.5

## **Codes/Mitigation Info/Possible Solution**

## Field Measurements/Component Compliance



Street 1 Name
Stop Condition-Street 1
Street 2 Name
Stop Condition-Street 2

SHERWOOD FOREST DR
StopSign
COLONY RD
None

Possible Solutions:

Remove & Replace Curb Ramp With
Two New Directional Ramps or
Equivalent.

Surveyor Notes:

LT RP < 5%

PROW/ADA:
R304.3.2

Total Cost: \$ 3200.00

Fleid Measurements/Component Compilance					
Compliance Description Data		Compliance Description		Data	
N/A	Ramp Length LT (in)	48.0	N/A	Ramp Length RT (in)	70.0
Yes	Ramp Width LT (in)	60.0	Yes	Ramp Width RT (in)	63.0
Yes	Ramp Slope LT (%)	2.4	No	Ramp Slope RT (%)	9.2
Yes	Ramp XSlope LT (%)	0.4	Yes	Ramp XSlope RT (%)	1.1
N/A	Landing Length (in)	N/A	N/A	DWS Provided?	N/A
N/A	Landing Width (in)	N/A	N/A	DWS Contrast?	N/A
N/A	Landing Slope (%)	N/A	N/A	DWS Length (in)	N/A
N/A	Landing X Slope (%)	N/A	N/A	DWS Full Width?	N/A
N/A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset (in)	N/A
N/A	Shared Landing?	N/A			
N/A	Gutter Ponding?	N/A	N/A	Gutter Slope (%)	N/A
N/A	Gutter Lip Ht (in)	N/A	N/A	Gutter X Slope (%)	N/A
N/A	Painted X Walk1?	No	N/A	Painted X Walk2?	No
	X Walk 1 Direction	To S		X Walk 2 Direction	То Е
N/A	X Walk 1 Width (in)	N/A	N/A	X Walk 2 Width (in)	N/A
	X Walk 1 Slope (%)	1.9		X Walk 2 Slope (%)	1.8
	X Walk 1 X Slope (%)	4.9		X Walk 2 X Slope (%)	0.4
N/A	Ramp inside XWalk1?	N/A	N/A	Ramp inside XWalk2?	N/A
	Road Slope (%)	5.8	N/A	Clear Space?	N/A
	Road X Slope (%)	3.9	N/A	Clear Space to XWalk (in)	N/A
N/A	Any Obstructions?	N/A	N/A	Storm Grate/Utility Hazard?	N/A
	Obstruction Type			Storm Grate/Utility Type	
		N/A			N/A
			Yes	Surface Condition? (G/P)	Good
			N/A	Curb Slope (%)	9.6





