

## **Access Compliance Report Public Rights-of-Way** (Curb Ramps)



Data

31.5

72.0

10.0

2.0

7.2

4.5

N/A

Intersection ID: 10262 Main Street: WOLFBERRY ST **Cross Street: BANCROFT ST** Location: S **Overall Compliance: No Severity Score:** 22.5 ADA ID: 0C8033355F40 Ramp Type: Combination1 Initial Pass/Fail: Fail

Compliance Description

N/A

Yes

Yes

Yes

N/A

No

N/A

Ramp Length LT (in)

Ramp Width LT (in)

Ramp Slope LT (%)

Ramp Length (in)

Ramp Width (in)

Flare Slope LT (%)

Landing Length (in)

Landing Width (in)

Landing Slope (%)

Landing X Slope (%)

Landing Curb? (Y/N)

Shared Landing?

**Gutter Ponding?** 

Gutter Lip Ht (in)

Painted X Walk1?

Flare Traversable LT?

Flare Type LT

Ramp XSlope LT (%)

**Codes/Mitigation Info/Possible Solution** 

## Field Measurements/Component Compliance

N/A

Yes

No

Yes

Yes

No

N/A

Compliance Description

Ramp Length RT (in)

Ramp Width RT (in)

Ramp Slope RT (%)

Ramp XSlope RT (%)

Ramp Slope (%)

Flare Type RT

Ramp XSlope (%)

Flare Slope RT (%)

DWS Provided?

**DWS Contrast?** 

DWS Length (in)

DWS Full Width?

DWS Offset (in)

Gutter Slope (%)

Gutter X Slope (%)

Painted X Walk2?

Flare Traversable RT?

Data

42.0

71.5

7.3

1.9

95.5

43.0

N/A

No



Street 1 Name StopSign **BANCROFT ST** Stop Condition-Street 1 N/A Street 2 Name Stop Condition-Street 2 N/A Possible Solutions: Remove & Replace Entire Ramp. Surveyor Notes: N/A PROW/ADA: Not Found, R304.5.1, R304.5.3, R304.3.2



Total Cost:



To N N/A X Walk 1 Direction X Walk 2 Direction X Walk 1 Width (in) N/A X Walk 2 Width (in) N/A 5.6 X Walk 2 Slope (%) N/A X Walk 1 Slope (%) X Walk 1 X Slope (%) 2.6 X Walk 2 X Slope (%) N/A N/A 1800.00 N/A Ramp inside XWalk1? N/A Ramp inside XWalk2? N/A Road Slope (%) N/A Clear Space? N/A Road X Slope (%) N/A N/A Clear Space to XWalk (in) N/A N/A Any Obstruction? N/A **Obstruction Type** N/A N/A Storm Grate/Utility Hazard? N/A Storm Grate/Utility Type N/A Yes Surface Condition? (G/P) Good 12.5 Curb Slope (%)