cole

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Yes

Surface Condition? (G/P)

Good

| Intersection ID: 28975 | Main Str | Main Street: BANNINGTON_RD | | Cross Street: NORTHBURY_LN | | | Location: | SW | |
|-------------------------|---------------------|---|--------|----------------------------|--|-----------------------------|-----------|-----------------------------|-------|
| ADA ID: 0D9047E1960C | Ramp Ty | Ramp Type: PerpDiag | | | Initial Pass/Fail: Fail Overall Compliance: No | | | o Severity Score: | 33.75 |
| Co | | Field Measurements/Component Compliance | | | | | | | |
| | des/mitigation into | /Possible Solution | | | | | | | Dete |
| MORTHEURY AN G | | Possible Solutions: | | Compliance Description | | Data Compliance Description | | | Data |
| | | Remove & Replace Curb Ramp V | Vith | N/A | Ramp Length (in) | 95.0 | Yes | Ramp Slope (%) | 6.2 |
| | | Two New Directional Ramps or | | No | Ramp Width (in) | 38.0 | No | Ramp XSlope (%) | 10.3 |
| | | Equivalent. | | N/A | Flare Type LT | N/A | N/A | Flare Type RT | N/A |
| | | | | N/A | Flare Slope LT (%) | N/A | N/A | Flare Slope RT (%) | N/A |
| | | | | N/A | Flare Traversable LT? | N/A | N/A | Flare Traversable RT? | N/A |
| LAN CA | | | | N/A | Landing Length (in) | N/A | N/A | DWS Provided? | N/A |
| | | Surveyor Notes: | | N/A | Landing Width (in) | N/A | N/A | DWS Contrast? | N/A |
| | | N/A | | N/A | Landing Slope (%) | N/A | N/A | DWS Length (in) | N/A |
| | | | | N/A | Landing X Slope (%) | N/A | N/A | DWS Full Width? | N/A |
| | | | | N/A | Landing Curb? (Y/N) | N/A | N/A | DWS Offset (in) | N/A |
| | | | | N/A | Shared Landing? | N/A | | | |
| 12 11 11 | | PROW/ADA: | | N/A | Gutter Ponding? | N/A | N/A | Gutter Slope (%) | N/A |
| 1. at 1. | Sur and | Not Found, R304.5.1, R304.5.3 | | N/A | Gutter Lip Ht (in) | N/A | N/A | Gutter X Slope (%) | N/A |
| | ST A | | | N/A | Painted X Walk1? | No | N/A | Painted X Walk2? | No |
| a straight of the | AN AN AN | | | | X Walk 1 Direction | To E | | X Walk 2 Direction | To N |
| | | | | N/A | X Walk 1 Width (in) | N/A | N/A | X Walk 2 Width (in) | N/A |
| Street 1 Name | BANNINGTON RD | | | | X Walk 1 Slope (%) | 2.6 | | X Walk 2 Slope (%) | 5.8 |
| Stop Condition-Street 2 | None | | | | X Walk 1 X Slope (%) | 5.1 | | X Walk 2 X Slope (%) | 2.8 |
| Street 2 Name | NORTHBURY LN | | | N/A | Ramp inside XWalk1? | N/A | N/A | Ramp inside XWalk2? | N/A |
| Stop Condition-Street 1 | StopSign | | | | Road Slope (%) | 6.2 | N/A | Clear Space? | N/A |
| | - | | | | Road X Slope (%) | 2.2 | N/A | Clear Space to XWalk (in) | N/A |
| | | | | N/A | Any Obstructions? | N/A | N/A | Storm Grate/Utility Hazard? | N/A |
| | | Total Cost: \$ 3 | 200.00 | | Obstruction Type | | | Storm Grate/Utility Type | |
| | | | | | | N/A | | | N/A |
| | | | | | | | 1 | | |

