

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Intersection ID: 2865Main Street:DOWNFIELD_WOOD_DRCross Street:LADY_BANK_DRLocation:EADA ID: 0EE5BC339809Ramp Type:PerpInitial Pass/Fail:FailOverall Compliance:NoSeverity Score:50

Codes/Mitigation Info/Possible Solution



Street 1 Name DOWNFIELD WOOD DR
Stop Condition-Street 2 None
Street 2 Name N/A
Stop Condition-Street 1 N/A

Possible Solutions:					
Remove & Replace Entire Ramp.					
Sumrayan Natao					
Surveyor Notes:					
N/A					
PROW/ADA:					
R304.2.2, R304.5.3					

Total Cost: \$ 1850.00

Field Measurements/Component Compliance						
Compliance Description		Data	Compliance Description		Data	
N/A	Ramp Length (in)	48.0	No	Ramp Slope (%)	19.1	
Yes	Ramp Width (in)	48.0	No	Ramp XSlope (%)	11.2	
N/A	Flare Type LT	N/A	N/A	Flare Type RT	N/A	
N/A	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)	N/A	
N/A	Flare Traversable LT?	N/A	N/A	Flare Traversable RT?	N/A	
N/A	Landing Length (in)	N/A	N/A	DWS Provided?	N/A	
N/A	Landing Width (in)	N/A	N/A	DWS Contrast?	N/A	
N/A	Landing Slope (%)	N/A	N/A	DWS Length (in)	N/A	
N/A	Landing X Slope (%)	N/A	N/A	DWS Full Width?	N/A	
N/A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset (in)	N/A	
N/A	Shared Landing?	N/A				
N/A	Gutter Ponding?	N/A	N/A	Gutter Slope (%)	N/A	
N/A	Gutter Lip Ht (in)	N/A	N/A	Gutter X Slope (%)	N/A	
N/A	Painted X Walk1?	No	N/A	Painted X Walk2?	N/A	
	X Walk 1 Direction	To W		X Walk 2 Direction	N/A	
N/A	X Walk 1 Width (in)	N/A	N/A	X Walk 2 Width (in)	N/A	
	X Walk 1 Slope (%)	7.0		X Walk 2 Slope (%)	N/A	
	X Walk 1 X Slope (%)	10.6		X Walk 2 X Slope (%)	N/A	
N/A	Ramp inside XWalk1?	N/A	N/A	Ramp inside XWalk2?	N/A	
	Road Slope (%)	N/A	N/A	Clear Space?	N/A	
	Road X Slope (%)	N/A	N/A	Clear Space to XWalk (in)	N/A	
N/A	Any Obstructions?	N/A	N/A	Storm Grate/Utility Hazard?	N/A	
	Obstruction Type			Storm Grate/Utility Type		
		N/A			N/A	
			Yes	Surface Condition? (G/P)	Good	
100						





