

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Intersection ID: 14629 Main Street: EASTWAY DR Cross Street: WOODLAND DR Location: NW **Overall Compliance: No Severity Score:** 10 ADA ID: 0FB164DC56BC Ramp Type: PerpDiag Initial Pass/Fail: Fail

Compliance Description

Ramp Length (in)

Ramp Width (in)

Flare Slope LT (%) Flare Traversable LT?

Landing Length (in)

Landing Width (in)

Landing Slope (%)

Landing X Slope (%)

Landing Curb? (Y/N)

Shared Landing?

Gutter Ponding?

Gutter Lip Ht (in)

Painted X Walk1?

X Walk 1 Direction

X Walk 1 Width (in)

X Walk 1 Slope (%)

X Walk 1 X Slope (%)

Ramp inside XWalk1?

Road Slope (%)

Road X Slope (%)

Any Obstructions?

Obstruction Type

Flare Type LT

N/A

No

N/A

N/A

Codes/Mitigation Info/Possible Solution

Field Measurements/Component Compliance

Yes

No

N/A

Yes

Data

39.0

47.5

N/A

Yes

To SW

108.0

1.0

3.8


Yes

1.9

3.6

N/A

N/A



WOODLAND DR Street 1 Name Stop Condition-Street 2 Signal **EASTWAY DR** Street 2 Name Stop Condition-Street 1 Signal Remove & Replace Curb Ramp With Two New Directional Ramps or Equivalent.

Possible Solutions:

| | | | | 14/74 |
|-----------------|----------------|------|---------|-------|
| | | | | N/A |
| | | | | N/A |
| Surveyor Notes: | | | | N/A |
| N/A | | | | N/A |
| | | | | N/A |
| | | | | N/A |
| | | | | N/A |
| PROW/ADA: | | | | N/A |
| Not Found, | R304.5.1, R304 | .5.3 | | N/A |
| | | | | N/A |
| Total Cost: | ; | \$ | 3200.00 | |

| | * | | |
|--|----------|---|--|
| | | | |
| | 1130 | C | |
| | | | |
| | | | |







Clear Space to XWalk (in)

Storm Grate/Utility Hazard?

Storm Grate/Utility Type

Surface Condition? (G/P)

N/A

N/A

N/A

Good