

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Intersection ID: 48560 Main Street: WOODLAND WATCH CT Cross Street: ARDREY WOODS DR Location: Ε **Overall Compliance: No Severity Score:** 25 ADA ID: 105A7A2D9683 Ramp Type: PerpDiag Initial Pass/Fail: Fail

Codes/Mitigation Info/Possible Solution

Field Measurements/Component Compliance

Yes

No

N/A

Yes

Compliance Description

Ramp Slope (%)

Flare Type RT

Ramp XSlope (%)

Flare Slope RT (%)

DWS Provided?

DWS Contrast?

DWS Length (in)

DWS Full Width?

DWS Offset (in)

Gutter Slope (%)

Gutter X Slope (%)

Painted X Walk2?

X Walk 2 Direction

X Walk 2 Width (in)

X Walk 2 Slope (%)

X Walk 2 X Slope (%)

Ramp inside XWalk2?

Clear Space to XWalk (in)

Storm Grate/Utility Type

Surface Condition? (G/P)

Storm Grate/Utility Hazard?

Clear Space?

Flare Traversable RT?

Data

51.0

48.0

N/A

No

N/A

7.0

5.5

N/A

8.3

1.1 N/A

N/A

To NW



Street 1 Name Stop Condition-Street 2 Street 2 Name Stop Condition-Street 1 WOODLAND WATCH CT None **ARDREY WOODS DR**

StopSign

Possible Solutions: Remove & Replace Curb Ramp With Two New Directional Ramps or Equivalent. Surveyor Notes: N/A

Not Found, R304.5.3

Total Cost:

Compliance Description N/A Yes N/A N/A

Ramp Length (in)

Ramp Width (in)

Flare Slope LT (%)

Landing Length (in)

Landing Width (in)

Landing Slope (%)

Landing X Slope (%)

Landing Curb? (Y/N)

Shared Landing?

Gutter Ponding?

Gutter Lip Ht (in)

Painted X Walk1?

X Walk 1 Direction

X Walk 1 Width (in)

X Walk 1 Slope (%)

X Walk 1 X Slope (%)

Ramp inside XWalk1?

Road Slope (%)

Road X Slope (%)

Any Obstructions?

Obstruction Type

Flare Traversable LT?

Flare Type LT

N/A

3200.00







Data

6.8

12.2

N/A

No

N/A

2.0

9.5

N/A

N/A

N/A

N/A

N/A

Good

To SW