

## **Access Compliance Report Public Rights-of-Way** (Curb Ramps)



Data

44.0

48.0

0.3

4.7

9.4

5.9

N/A

Intersection ID: 11186 Main Street: CARDIFF AV Cross Street: SHAMROCK DR Location: SW Initial Pass/Fail: Fail **Overall Compliance: No Severity Score:** ADA ID: 112E5F6459CA Ramp Type: Combination1 37.5

Compliance Description

Ramp Length LT (in)

Ramp Width LT (in)

Ramp Slope LT (%)

Ramp Length (in)

Ramp Width (in)

Flare Slope LT (%)

Landing Length (in)

Landing Width (in)

Landing Slope (%)

Landing X Slope (%)

Landing Curb? (Y/N)

Shared Landing?

**Gutter Ponding?** 

Gutter Lip Ht (in)

Painted X Walk1?

Flare Traversable LT?

Flare Type LT

Ramp XSlope LT (%)

N/A

Yes

No

No

N/A

Yes

N/A

**Codes/Mitigation Info/Possible Solution** 

## **Field Measurements/Component Compliance**

N/A

Yes

Yes

No

N/A

Compliance Description

Ramp Length RT (in)

Ramp Width RT (in)

Ramp Slope RT (%)

Ramp Slope (%)

Flare Type RT

Ramp XSlope (%)

Flare Slope RT (%)

DWS Provided?

**DWS Contrast?** 

DWS Length (in)

DWS Full Width?

DWS Offset (in)

Gutter Slope (%)

Gutter X Slope (%)

Painted X Walk2?

Flare Traversable RT?

Ramp XSlope RT (%)

Data

46.0

48.0

12.0

3.6

25.5 No

48.0 No

N/A

No



StopSign Street 1 Name **CARDIFF AV** Stop Condition-Street 1 Street 2 Name N/A Stop Condition-Street 2 N/A Possible Solutions: Remove & Replace Entire Ramp. Surveyor Notes: RT RP < 5% PROW/ADA: Not Found, R304.2.2, R304.5.3, R304.3.2



Total Cost:



		X Walk 1 Direction	To SE		X Walk 2 Direction	N/A
		X Walk 1 Width (in)	N/A		X Walk 2 Width (in)	N/A
		X Walk 1 Slope (%)	1.4		X Walk 2 Slope (%)	N/A
		X Walk 1 X Slope (%)	3.8		X Walk 2 X Slope (%)	N/A
1800.00	N/A	Ramp inside XWalk1?	N/A	N/A	Ramp inside XWalk2?	N/A
		Road Slope (%)	N/A		Clear Space?	N/A
		Road X Slope (%)	N/A	N/A	Clear Space to XWalk (in)	N/A
				N/A	Any Obstruction?	N/A
		The state of			Obstruction Type	
60						N/A
				N/A	Storm Grate/Utility Hazard?	N/A
					Storm Grate/Utility Type	N/A
						N/A
			Yes	Surface Condition? (G/P)	Good	
					Curb Slope (%)	15.5