

## **Access Compliance Report Public Rights-of-Way** (Curb Ramps)



Data

8.8

5.1

N/A

Good

Intersection ID: N/A Main Street: ELMSTONE DR Cross Street: THORNHILL CLUB DR Location: NE **Overall Compliance: No ADA ID: 115E1F72F190** Ramp Type: Perp Initial Pass/Fail: Fail Severity Score: 33.75

**Codes/Mitigation Info/Possible Solution** 

## Field Measurements/Component Compliance

No

No

N/A

Yes

Compliance Description

Ramp Slope (%)

Flare Type RT

Ramp XSlope (%)

Flare Slope RT (%)

**DWS Provided?** 

**DWS Contrast?** 

DWS Length (in)

DWS Full Width?

DWS Offset (in)

Gutter Slope (%)

Gutter X Slope (%)

Painted X Walk2?

X Walk 2 Direction

X Walk 2 Width (in)

X Walk 2 Slope (%)

X Walk 2 X Slope (%)

Ramp inside XWalk2?

Clear Space to XWalk (in)

Storm Grate/Utility Hazard?

Storm Grate/Utility Type

Surface Condition? (G/P)

Clear Space?

Flare Traversable RT?

Data

92.0

47.5

N/A

No

N/A

2.1

4.9

N/A

N/A

N/A

N/A

N/A

To SE



**ELMSTONE DR** Street 1 Name Stop Condition-Street 2 None N/A Street 2 Name Stop Condition-Street 1 N/A Possible Solutions: Compliance Description N/A Remove & Replace Entire Ramp. No N/A N/A Surveyor Notes: N/A PROW/ADA: R304.5.1, R304.2.2, R304.5.3

Total Cost: 1850.00

N/A Flare Traversable LT? N/A Landing Length (in) N/A Landing Width (in) N/A Landing Slope (%) N/A Landing X Slope (%) N/A Landing Curb? (Y/N) N/A Shared Landing? N/A **Gutter Ponding?** N/A Gutter Lip Ht (in) N/A Painted X Walk1? X Walk 1 Direction N/A X Walk 1 Width (in) X Walk 1 Slope (%) X Walk 1 X Slope (%) N/A Ramp inside XWalk1? Road Slope (%) Road X Slope (%) N/A

Ramp Length (in)

Ramp Width (in)

Flare Slope LT (%)

Flare Type LT

Any Obstructions? **Obstruction Type** 



