cole

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Intersection ID: 13784	Main Str	eet: MORNINGSIDE_DR	Cross	Street:	IVEY_DR	Location:	SW		
ADA ID: 127AF45DD214	Ramp Type: PerpDiag			nitial Pass/Fail: Fail Overall Compliance: No				o Severity Score:	13.75
Codes/Mitigation Info/Possible Solution				Field Measurements/Component Compliance					
		Possible Solutions:		Compliance Description Da			a Compliance Description		Data
		Remove & Replace Curb Ramp V	Vith	N/A	Ramp Length (in)	47.5	No	Ramp Slope (%)	9.2
		Two New Directional Ramps or Equivalent.		Yes	Ramp Width (in)	48.0	No	Ramp XSlope (%)	2.7
				N/A	Flare Type LT	N/A	N/A	Flare Type RT	N/A
				N/A	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)	N/A
				N/A	Flare Traversable LT?	N/A	N/A	Flare Traversable RT?	N/A
				N/A	Landing Length (in)	N/A	N/A	DWS Provided?	N/A
		Surveyor Notes:		N/A	Landing Width (in)	N/A	N/A	DWS Contrast?	N/A
		N/A		N/A	Landing Slope (%)	N/A	N/A	DWS Length (in)	N/A
				N/A	Landing X Slope (%)	N/A	N/A	DWS Full Width?	N/A
				N/A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset (in)	N/A
				N/A	Shared Landing?	N/A			
		PROW/ADA:		N/A	Gutter Ponding?	N/A	N/A	Gutter Slope (%)	N/A
		R304.2.2, R304.5.3		N/A	Gutter Lip Ht (in)	N/A	N/A	Gutter X Slope (%)	N/A
		,		N/A	Painted X Walk1?	No	N/A	Painted X Walk2?	No
	Mr. N Marchine				X Walk 1 Direction	To E		X Walk 2 Direction	To N
and the second second	THE REAL			N/A	X Walk 1 Width (in)	N/A	N/A	X Walk 2 Width (in)	N/A
Street 1 Name	MORNINGSIDE DR	_			X Walk 1 Slope (%)	3.5		X Walk 2 Slope (%)	3.7
Stop Condition-Street 2	None				X Walk 1 X Slope (%)	1.1		X Walk 2 X Slope (%)	0.6
Street 2 Name	IVEY DR			N/A	Ramp inside XWalk1?	N/A	N/A	Ramp inside XWalk2?	N/A
Stop Condition-Street 1	StopSign				Road Slope (%)	4.4	N/A	Clear Space?	N/A
					Road X Slope (%)	0.2	N/A	Clear Space to XWalk (in)	N/A
				N/A	Any Obstructions?	N/A	N/A	Storm Grate/Utility Hazard?	N/A
		Total Cost: \$	3200.00		Obstruction Type			Storm Grate/Utility Type	
						N/A			N/A

Yes Surface Condition? (G/P)

Good



