

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Good

Intersection ID: 15111	Main Str	eet: SHEFFIELD_DR	Cross Street: TARRINGTON_AV				Location:	Е
ADA ID: 12FDE802026E		/pe: Perp	Initial Pass/Fail: Fail Overall Complian			nce: N		
Codes/Mitigation Info/Possible Solution			Field Measurements/Component Compliance					
Possible Solutions:			Compliance Description Data Compliance					Data
- 3 See -		Remove & Replace Entire Ramp.					Ramp Slope (%)	5.4
And Andrew Andrew	al a	Remove & Replace Entire Ramp.	No	Ramp Width	()		Ramp XSlope (%)	2.8
ELT OF T	AN AN		N/A	Flare Type I			Flare Type RT	N/A
	S		N/A				Flare Slope RT (%)	N/A
The state of the s	110.00		N/A				Flare Traversable RT?	N/A
	the production		N/A				DWS Provided?	N/A
6	612	Surveyor Notes:	N/A	5	S ()		DWS Contrast?	N/A
OF T	X 1 8		N/A	8	()		DWS Length (in)	N/A
	A AP	N/A	N/A	5	,		DWS Full Width?	N/A
the second se	1 4 1		N/A N/A	-				N/A N/A
	***/			8			DWS Offset (in)	N/A
	A CARLER		N/A		0			
		PROW/ADA:	N/A		-		Gutter Slope (%)	N/A
		R304.5.1, R304.5.3	N/A	Gutter Lip H	. ,		Gutter X Slope (%)	N/A
A DAMAS COLORD	A Star		N/A				Painted X Walk2?	N/A
	1 20 1 10			X Walk 1 Di	rection To NV	'	X Walk 2 Direction	N/A
and the second s]	N/A	X Walk 1 Wi	idth (in) N/A	N/A	X Walk 2 Width (in)	N/A
Street 1 Name	TARRINGTON AV			X Walk 1 Slo	ope (%) 2.0		X Walk 2 Slope (%)	N/A
Stop Condition-Street 2	StopSign			X Walk 1 X	Slope (%) 1.0	;	X Walk 2 X Slope (%)	N/A
Street 2 Name	N/A		N/A	Ramp inside	XWalk1? N/	N/A	Ramp inside XWalk2?	N/A
Stop Condition-Street 1	N/A			Road Slope	(%) N//	N/A	Clear Space?	N/A
				Road X Slop	oe (%) N/A	N/A	Clear Space to XWalk (in)	N/A
			N/A	Any Obstruc	ctions? N/	N/A	Storm Grate/Utility Hazard?	N/A
		Total Cost: \$ 1	850.00	Obstruction	Туре		Storm Grate/Utility Type	
					N//			N/A

Yes Surface Condition? (G/P)

