

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Intersection ID: 3097Main Street: PLACER_MAPLE_LNCross Street: ALLEN_A_BROWN_RDLocation: NWADA ID: 13A45B809F58Ramp Type: PerpDiagInitial Pass/Fail: Fail Overall Compliance: No Severity Score: 10

Codes/Mitigation Info/Possible Solution

Field Measurements/Component Compliance



Street 1 Name
Stop Condition-Street 2
Street 2 Name
Stop Condition-Street 1

ALLEN A BROWN RD None PLACER MAPLE LN StopSign Possible Solutions:

Remove & Replace Curb Ramp With
Two New Directional Ramps or
Equivalent.

Surveyor Notes:

N/A

PROW/ADA:

Not Found, R304.5.1, R304.5.3

Total Cost: \$ 3200.00

Compliance Description		Data	Comp	liance	Description	Data
N/A	Ramp Length (in)	50.0	Yes	Ram	Slope (%)	7.8
No	Ramp Width (in)	47.0	No	Ramp XSlope (%)		4.0
N/A	Flare Type LT	N/A	N/A	Flare Type RT		N/A
N/A	Flare Slope LT (%)	N/A	N/A	Flare	Slope RT (%)	N/A
N/A	Flare Traversable LT?	N/A	N/A	Flare	Traversable RT?	N/A
N/A	Landing Length (in)	N/A	N/A	DWS	Provided?	N/A
N/A	Landing Width (in)	N/A	N/A	DWS	Contrast?	N/A
N/A	Landing Slope (%)	N/A	N/A	DWS	Length (in)	N/A
N/A	Landing X Slope (%)	N/A	N/A	DWS	Full Width?	N/A
N/A	Landing Curb? (Y/N)	N/A	N/A	DWS	Offset (in)	N/A
N/A	Shared Landing?	N/A				
N/A	Gutter Ponding?	N/A	N/A	Gutte	er Slope (%)	N/A
N/A	Gutter Lip Ht (in)	1.0	N/A	Gutte	r X Slope (%)	N/A
N/A	Painted X Walk1?	No	N/A	Paint	ed X Walk2?	No
	X Walk 1 Direction	To S		X Wa	lk 2 Direction	To E
N/A	X Walk 1 Width (in)	N/A	N/A	X Wa	lk 2 Width (in)	N/A
	X Walk 1 Slope (%)	0.8		X Wa	lk 2 Slope (%)	6.9
	X Walk 1 X Slope (%)	6.6		X Wa	lk 2 X Slope (%)	0.9
N/A	Ramp inside XWalk1?	N/A	N/A	Ramı	inside XWalk2?	N/A
	Road Slope (%)	4.9	N/A	Clear	Space?	N/A
	Road X Slope (%)	5.4	N/A	Clear	Space to XWalk (in)	N/A
N/A	Any Obstructions?	N/A	N/A	Storn	n Grate/Utility Hazard?	N/A
	Obstruction Type			Storn	n Grate/Utility Type	
		N/A				N/A
			Yes	Surfa	ce Condition? (G/P)	Good





