cole

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Yes

No

Surface Condition? (G/P)

Curb Slope (%)

Good

11.1

| | | | | | | Location | W/ | |
|---|--|---------------|---|----------|--------|-----------------------------|-----|--|
| Intersection ID: 10161 Mai | Main Street: E_35TH_ST | | Cross Street: YADKIN_AV | | | Location: | W | |
| ADA ID: 1417E6B17C15 Ran | np Type: BlendTrans2 | Initial Pass/ | Fail: Fail Overall | Complian | nce: N | o Severity Score: | 30 | |
| Codes/Mitigation Info/Possible Solution | | | Field Measurements/Component Compliance | | | | | |
| | Possible Solutions: | Con | Compliance Description Data | | | Compliance Description Data | | |
| | Remove & Replace Curb Ramp V Two New Directional Ramps or | Nith N/A | Ramp Length (in) | 83.5 | Yes | BlendTrans Slope (%) | 4.3 | |
| | | No | Ramp Width (in) | 35.5 | No | BlendTrans XSlope (%) | 5.5 | |
| | Equivalent. | N/A | Flare Type LT | N/A | N/A | Flare Type RT | N/A | |
| | | N/A | Flare Slope LT (%) | N/A | N/A | Flare Slope RT (%) | N/A | |
| | | N/A | Flare Traversable LT? | N/A | N/A | Flare Traversable RT? | N/A | |
| the second se | | N/A | Landing Length (in) | N/A | N/A | DWS Provided? | N/A | |
| | Surveyor Notes: | N/A | Landing Width (in) | N/A | N/A | DWS Contrast? | N/A | |
| | N/A | N/A | Landing Slope (%) | N/A | N/A | DWS Length (in) | N/A | |
| | | N/A | Landing X Slope (%) | N/A | N/A | DWS Full Width? | N/A | |
| Star Carl | | N/A | Landing Curb? (Y/N) | N/A | N/A | DWS Offset (in) | N/A | |
| | and the second sec | N/A | Shared Landing? | N/A | | | | |
| | PROW/ADA: | N/A | Gutter Ponding? | N/A | N/A | Gutter Slope (%) | N/A | |
| A A A A A A A A A A A A A A A A A A A | Not Found, R304.5.1, R304.5.3 | N/A | Gutter Lip Ht (in) | N/A | N/A | Gutter X Slope (%) | N/A | |
| 1 1 1 1 5 5 | | N/A | Painted X Walk1? | No | N/A | Painted X Walk2? | N/A | |
| A COURSE OF A CONSTRUCTION | | | X Walk 1 Direction | To SE | | X Walk 2 Direction | N/A | |
| | and the second se | | X Walk 1 Width (in) | N/A | | X Walk 2 Width (in) | N/A | |
| Street 1 Name YADKIN | AV | | X Walk 1 Slope (%) | 3.1 | | X Walk 2 Slope (%) | N/A | |
| Stop Condition-Street 1 | one | | X Walk 1 X Slope (%) | 2.7 | | X Walk 2 X Slope (%) | N/A | |
| Street 2 Name | N/A | N/A | Ramp inside XWalk1? | N/A | N/A | Ramp inside XWalk2? | N/A | |
| Stop Condition-Street 2 | N/A | | Road Slope (%) | 2.7 | | Clear Space? | N/A | |
| | | | Road X Slope (%) | 3.1 | N/A | Clear Space to XWalk (in) | N/A | |
| | | N/A | Any Obstructions? | N/A | N/A | Storm Grate/Utility Hazard? | N/A | |
| | Total Cost: \$ 3 | 200.00 | Obstruction Type | | | Storm Grate/Utility Type | | |
| | | | 2. | N/A | | | N/A | |

