

## Access Compliance Report Public Rights-of-Way (Curb Ramps)



Yes

Surface Condition? (G/P)

Good

Intersection ID: 13800	Main Street: CENTRAL_AV			Street:	TEMPLE_LN	Location:	NW		
ADA ID: 1455D884F2ED	Ramp Type: Perp			Initial Pass/Fail: Fail Overall Compliance: No				o Severity Score:	31.25
Codes/Mitigation Info/Possible Solution				Field Measurements/Component Compliance					
Possible Solutions:				Compliance Description Data Compliance Description					Data
and a state of the second		Remove & Replace Entire Rar	np.	N/A	Ramp Length (in)	59.0	No	Ramp Slope (%)	8.5
A DELEAST A.	a give the second			No	Ramp Width (in)	35.0	No	Ramp XSlope (%)	3.0
				N/A	Flare Type LT	N/A	N/A	Flare Type RT	N/A
				N/A	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)	N/A
	and in some			N/A	Flare Traversable LT?	N/A	N/A	Flare Traversable RT?	N/A
	Carlin and and and and			N/A	Landing Length (in)	N/A	N/A	DWS Provided?	N/A
	and the second	Surveyor Notes:		N/A	Landing Width (in)	N/A	N/A	DWS Contrast?	N/A
L -	<u>ь</u>	N/A		N/A	Landing Slope (%)	N/A	N/A	DWS Length (in)	N/A
and proceedings of the second s				N/A	Landing X Slope (%)	N/A	N/A	DWS Full Width?	N/A
GENTRAL AV				N/A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset (in)	N/A
	0.0			N/A	Shared Landing?	N/A			
	No.	PROW/ADA:		N/A	Gutter Ponding?	N/A	N/A	Gutter Slope (%)	N/A
And the supervised outputted in \$2.00 million	and a summer the second	Not Found, R304.5.1, R304.2.	2.	N/A	Gutter Lip Ht (in)	N/A	N/A	Gutter X Slope (%)	N/A
Martin Stansmithant	and the second	R304.5.3	_,	N/A	Painted X Walk1?	No	N/A	Painted X Walk2?	N/A
	ALC: NO PARTY				X Walk 1 Direction	To E		X Walk 2 Direction	N/A
				N/A	X Walk 1 Width (in)	N/A	N/A	X Walk 2 Width (in)	N/A
Street 1 Name	TEMPLE LN	-			X Walk 1 Slope (%)	1.6		X Walk 2 Slope (%)	N/A
Stop Condition-Street 2	StopSign				X Walk 1 X Slope (%)	3.0		X Walk 2 X Slope (%)	N/A
Street 2 Name	N/A			N/A	Ramp inside XWalk1?	N/A	N/A	Ramp inside XWalk2?	N/A
Stop Condition-Street 1	N/A				Road Slope (%)	N/A	N/A	Clear Space?	N/A
					Road X Slope (%)	N/A	N/A	Clear Space to XWalk (in)	N/A
				N/A	Any Obstructions?	N/A	N/A	Storm Grate/Utility Hazard?	N/A
		Total Cost: \$	1850.00		Obstruction Type			Storm Grate/Utility Type	
						N/A			N/A

