

## Access Compliance Report Public Rights-of-Way (Curb Ramps)



Intersection ID: 17126 Main Street: MISSION\_HILLS\_RD Cross Street: TEABERRY\_CT Location: NW

ADA ID: 147070C9BA96 Ramp Type: PerpDiag Initial Pass/Fail: Fail Overall Compliance: No Severity Score: 12.5

Codes/Mitigation Info/Possible Solution

## Field Measurements/Component Compliance



Street 1 Name MISSION HILLS RD
Stop Condition-Street 2 None
Street 2 Name TEABERRY CT
Stop Condition-Street 1 StopSign

Possible Solutions:

Remove & Replace Curb Ramp With Two New Directional Ramps or Equivalent.

Surveyor Notes:

N/A

PROW/ADA:

Not Found, R304.2.2

N/A Yes N/A N/A

Compliance Description Data Compliance Description Data No Ramp Length (in) 48.0 Ramp Slope (%) 9.0 Yes Ramp XSlope (%) Ramp Width (in) 48.0 1.9 N/A Flare Type LT N/A Flare Type RT N/A Flare Slope LT (%) N/A N/A Flare Slope RT (%) N/A Flare Traversable LT? N/A N/A Flare Traversable RT? N/A N/A N/A **DWS Provided?** N/A Landing Length (in) Landing Width (in) N/A N/A **DWS Contrast?** N/A N/A N/A Landing Slope (%) DWS Length (in) N/A Landing X Slope (%) N/A N/A DWS Full Width? N/A Landing Curb? (Y/N) N/A N/A DWS Offset (in) N/A N/A Shared Landing? **Gutter Ponding?** N/A N/A Gutter Slope (%) N/A Gutter Lip Ht (in) N/A N/A Gutter X Slope (%) N/A Painted X Walk1? No N/A Painted X Walk2? No X Walk 1 Direction To S X Walk 2 Direction To E N/A X Walk 2 Width (in) X Walk 1 Width (in) N/A X Walk 1 Slope (%) 1.9 X Walk 2 Slope (%) 1.1 X Walk 1 X Slope (%) 1.0 X Walk 2 X Slope (%) 0.5 N/A N/A Ramp inside XWalk2? N/A Ramp inside XWalk1? Road Slope (%) 1.9 N/A Clear Space? N/A N/A Road X Slope (%) 0.1 Clear Space to XWalk (in) N/A N/A N/A Any Obstructions? Storm Grate/Utility Hazard? N/A **Obstruction Type** Storm Grate/Utility Type N/A N/A Yes Surface Condition? (G/P) Good





Total Cost:



3200.00