cole

Access Compliance Report Public Rights-of-Way (Curb Ramps)



N/A

Curb Slope (%)

9.8

| | | • | | | | | | | |
|---|--|-------------------------|---------|--|----------------------|-------|-----------------------------|-----------------------------|-------|
| Intersection ID: 1003 | ntersection ID: 10034609 Main Street: PLANTATION_CENTER_DR | | | | Cross Street: N/A | | | | SW |
| ADA ID: 1579A30AA59B Ramp Type: Para | | | | Initial Pass/Fail: Fail Overall Compliance: No | | | | o Severity Score: | 13.75 |
| Codes/Mitigation Info/Possible Solution | | | | Field Measurements/Component Compliance | | | | | |
| | (PLAN) | Possible Solutions: | | Compliance Description Data | | | Compliance Description Data | | |
| | 0 | Remove & Replace Entire | Ramp. | N/A | Ramp Length LT (in) | 54.0 | N/A | Ramp Length RT (in) | 55.0 |
| | the second second | | | Yes | Ramp Width LT (in) | 108.0 | Yes | Ramp Width RT (in) | 108.0 |
| | 5. C. | | | No | Ramp Slope LT (%) | 8.9 | Yes | Ramp Slope RT (%) | 5.4 |
| | WILER DIS | | | Yes | Ramp XSlope LT (%) | 1.8 | No | Ramp XSlope RT (%) | 3.7 |
| TON | Gaut | - | | N/A | Landing Length (in) | N/A | N/A | DWS Provided? | N/A |
| PLANTAUL | A CONT | | | N/A | Landing Width (in) | N/A | N/A | DWS Contrast? | N/A |
| 37 | 6 miles | Surveyor Notes: | | N/A | Landing Slope (%) | N/A | N/A | DWS Length (in) | N/A |
| 190 | | N/A | | N/A | Landing X Slope (%) | N/A | N/A | DWS Full Width? | N/A |
| 10 100 | | | | N/A | Landing Curb? (Y/N) | N/A | N/A | DWS Offset (in) | N/A |
| | | | | N/A | Shared Landing? | N/A | | () | |
| 1 20 0 40 | | | | N/A | Gutter Ponding? | N/A | N/A | Gutter Slope (%) | N/A |
| 19 20 : | PROW/ADA: | | N/A | Gutter Lip Ht (in) | N/A | N/A | Gutter X Slope (%) | N/A | |
| | 25 19 | R304.3.2, R304.5.3 | | N/A | Painted X Walk1? | No | N/A | Painted X Walk2? | N/A |
| 193 P | | , | | | X Walk 1 Direction | To NE | | X Walk 2 Direction | N/A |
| | | | | N/A | X Walk 1 Width (in) | N/A | N/A | X Walk 2 Width (in) | N/A |
| | | | | | X Walk 1 Slope (%) | 0.2 | | X Walk 2 Slope (%) | N/A |
| Street 1 Name | PLANTATION CENTER DR | | | | X Walk 1 X Slope (%) | 3.7 | | X Walk 2 X Slope (%) | N/A |
| Stop Condition-Street 1 | StopSign | | | N/A | Ramp inside XWalk1? | N/A | N/A | Ramp inside XWalk2? | N/A |
| Street 2 Name | N/A | | | | Road Slope (%) | N/A | N/A | Clear Space? | N/A |
| Stop Condition-Street 2 | N/A | | | | Road X Slope (%) | N/A | N/A | Clear Space to XWalk (in) | N/A |
| | | | | N/A | Any Obstructions? | N/A | N/A | Storm Grate/Utility Hazard? | N/A |
| | | | | | Obstruction Type | | | Storm Grate/Utility Type | |
| | | Total Cost: | \$ 1600 |).00 | | N/A | | | N/A |
| | | | | | | | Yes | Surface Condition? (G/P) | Good |

