cole

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Intersection ID: 2022 Main St		Cross S	troot	DEDSTART CT			Location	NW
	Main Street: DOWNFIELD_WOOD_DR		Cross Street: REDSTART_CT				Location:	
ADA ID: 15D497FFABD3 Ramp T	Ramp Type: PerpDiag			il: Fail Overall C	Severity Score:	8.75		
Codes/Mitigation Info/Possible Solution			Field Measurements/Component Compliance					
	Possible Solutions:		Compliance Description			Data Compliance Description		
	Remove & Replace Curb Ramp W	Vith	N/A	Ramp Length (in)	49.0	Yes	Ramp Slope (%)	6.7
	Two New Directional Ramps or Equivalent.		No	Ramp Width (in)	47.0	Yes	Ramp XSlope (%)	1.0
			N/A	Flare Type LT	N/A	N/A	Flare Type RT	N/A
	1		N/A	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)	N/A
			N/A	Flare Traversable LT?	N/A	N/A	Flare Traversable RT?	N/A
			N/A	Landing Length (in)	N/A	N/A	DWS Provided?	N/A
	Surveyor Notes:		N/A	Landing Width (in)	N/A	N/A	DWS Contrast?	N/A
	N/A		N/A	Landing Slope (%)	N/A	N/A	DWS Length (in)	N/A
			N/A	Landing X Slope (%)	N/A	N/A	DWS Full Width?	N/A
			N/A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset (in)	N/A
	1		N/A	Shared Landing?	N/A			
	PROW/ADA:		N/A	Gutter Ponding?	N/A	N/A	Gutter Slope (%)	N/A
	Not Found, R304.5.1		N/A	Gutter Lip Ht (in)	N/A	N/A	Gutter X Slope (%)	N/A
	·		N/A	Painted X Walk1?	No	N/A	Painted X Walk2?	No
				X Walk 1 Direction	To S		X Walk 2 Direction	To E
			N/A	X Walk 1 Width (in)	N/A	N/A	X Walk 2 Width (in)	N/A
Street 1 Name REDSTART CT				X Walk 1 Slope (%)	0.9		X Walk 2 Slope (%)	1.1
Stop Condition-Street 2 StopSign				X Walk 1 X Slope (%)	1.5		X Walk 2 X Slope (%)	1.5
Street 2 Name DOWNFIELD WOOD DR			N/A	Ramp inside XWalk1?	N/A	N/A	Ramp inside XWalk2?	N/A
Stop Condition-Street 1 None				Road Slope (%)	0.6	N/A	Clear Space?	N/A
				Road X Slope (%)	1.6	N/A	Clear Space to XWalk (in)	N/A
			N/A	Any Obstructions?	N/A	N/A	Storm Grate/Utility Hazard?	N/A
	Total Cost: \$ 32	200.00		Obstruction Type			Storm Grate/Utility Type	
					N/A			N/A

Yes Surface Condition? (G/P)

Good

