


Intersection ID: 14156	Main Street: BEECH_NUT_RD	Cross Street: HENDREN_AV	Location:	SE
ADA ID: 15FEEC64494E	Ramp Type: PerpDiag	Initial Pass/Fail: Fail	Overall Compliance: No	Severity Score: 12.5

Codes/Mitigation Info/Possible Solution			Field Measurements/Component Compliance					
	Possible Solutions:		Compliance	Description	Data	Compliance	Description	Data
	Remove & Replace Curb Ramp With Two New Directional Ramps or Equivalent.		N/A	Ramp Length (in)	88.0	Yes	Ramp Slope (%)	5.3
			Yes	Ramp Width (in)	48.0	No	Ramp XSlope (%)	5.3
			N/A	Flare Type LT	N/A	N/A	Flare Type RT	N/A
	Surveyor Notes:  N/A		N/A	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)	N/A
			N/A	Flare Traversable LT?	N/A	N/A	Flare Traversable RT?	N/A
			N/A	Landing Length (in)	N/A	N/A	DWS Provided?	N/A
			N/A	Landing Width (in)	N/A	N/A	DWS Contrast?	N/A
			N/A	Landing Slope (%)	N/A	N/A	DWS Length (in)	N/A
			N/A	Landing X Slope (%)	N/A	N/A	DWS Full Width?	N/A
N/A			Landing Curb? (Y/N)	N/A	N/A	DWS Offset (in)	N/A	
N/A			Shared Landing?	N/A				
N/A			Gutter Ponding?	N/A	N/A	Gutter Slope (%)	N/A	
PROW/ADA:  R304.5.3		N/A	Gutter Lip Ht (in)	N/A	N/A	Gutter X Slope (%)	N/A	
		N/A	Painted X Walk1?	No	N/A	Painted X Walk2?	No	
			X Walk 1 Direction	To N		X Walk 2 Direction	To W	
		N/A	X Walk 1 Width (in)	N/A	N/A	X Walk 2 Width (in)	N/A	
			X Walk 1 Slope (%)	6.9		X Walk 2 Slope (%)	1.3	
			X Walk 1 X Slope (%)	1.7		X Walk 2 X Slope (%)	4.4	
		N/A	Ramp inside XWalk1?	N/A	N/A	Ramp inside XWalk2?	N/A	
			Road Slope (%)	1.9	N/A	Clear Space?	N/A	
			Road X Slope (%)	3.7	N/A	Clear Space to XWalk (in)	N/A	
		N/A	Any Obstructions?	N/A	N/A	Storm Grate/Utility Hazard?	N/A	
Total Cost:		\$	3200.00					
		</						

