

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Intersection ID: 14441	Main Street: E_KINGSTON_AV			Cross Street: SPRINGDALE_AV				Location:	w	
ADA ID: 16684A1E7941	Ramp Type: Directional1			Initial Pass/Fail: Fail Overall Compliance			nce: N	o Severity Score:	28.75	
Codes/Mitigation Info/Possible Solution			Field Measurements/Component Compliance							
	Possible Solutions:		Compliance Description				Data Compliance Description			
ALL A AND MARK		Remove & Replace	Entire Ramp		N/A	Ramp Length (in)	99.0	N/A	Grade Break?	N/A
A CALL AND A CONTRACT	Sen /				Yes	Ramp Width (in)	48.0	N/A	Grade Break Slope (%)	0.0
Ra Part	The second second	S .			No	Ramp Slope (%)	8.7	N/A	Grade Break XSlope (%)	0.0
	*/				No	Ramp XSlope (%)	2.4			
					N/A	Flare Type LT	N/A	N/A	Flare Type RT	N/A
the second secon	ST.				N/A	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)	0.0
the second se	First we	Surveyor Notes:			N/A	Flare Traversable LT?	N/A	N/A	Flare Traversable RT?	N/A
	Ser 1	DAMAGED CURB/C	TR/RAMP		N/A	Landing Length (in)	0.0	N/A	DWS Provided?	N/A
E B	2 80 1				N/A	Landing Width (in)	0.0	N/A	DWS Contrast?	N/A
		÷			N/A	Landing Slope (%)	0.0	N/A	DWS Length (in)	N/A
	A. /				N/A	Landing X Slope (%)	0.0	N/A	DWS Full Width?	N/A
Star Star	Alta.	PROW/ADA:			N/A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset LT (in)	N/A
	16-11	R304.2.2, R304.5.3,	R302 7		N/A	Shared Landing?	N/A	N/A	DWS Offset RT (in)	N/A
	141	1.000-1.2.2, 1.000-1.010,			N/A	Gutter Ponding?	0.0	N/A	Gutter Slope (%)	N/A
	· And	4			N/A	Gutter Lip Ht (in)	1.0	N/A	Gutter X Slope (%)	N/A
10 - stand 1 is the	AL.				N/A	Painted X Walk1?	No		Road Slope (%)	1.1
Street 1 Name SPRI	NGDALE AV	-				X Walk 1 Direction	To SE		Road X Slope (%)	2.9
Stop Condition-Street 1	StopSign					X Walk 1 Width (in)	N/A		Clear Space?	N/A
Street 2 Name	N/A					X Walk 1 Slope (%)	1.1	N/A	Clear Space to XWalk (in)	N/A
Stop Condition-Street 2	N/A					X Walk 1 X Slope (%)	2.9	N/A	Storm Grate/Utility Hazard?	N/A
					N/A	Ramp inside XWalk1?	N/A		Storm Grate/Utility Type	
					N/A	Any Obstructions?	N/A		5 51	N/A
		Total Cost:	\$ 1	600.00		Obstruction Type		No	Surface Condition? (G/P)	Poor
							N/A	N/A	Curb Slope (%)	12.7

