

## Access Compliance Report Public Rights-of-Way (Curb Ramps)



Good

Intersection ID: 2838	Main Street: FOGGY_MEADOW_RD			treet:	LONG_FOREST_DR	Location:	SE			
ADA ID: 18C8BF62017B				Initial Pass/Fail: Fail Overall Compliance: No				o Severity Score:	13.75	
Codes/Mitigation Info/Possible Solution				Field Measurements/Component Compliance						
		Possible Solutions:		Compliance Description Data Compliance Descr					Data	
provide the second seco	the liter	Remove & Replace Entire Ramp	).	N/A	Ramp Length (in)	47.0	No	Ramp Slope (%)	10.7	
	A main	······	-	Yes	Ramp Width (in)	48.0	No	Ramp XSlope (%)	4.7	
				N/A	Flare Type LT	N/A	N/A	Flare Type RT	N/A	
				N/A	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)	N/A	
	The second second			N/A	Flare Traversable LT?	N/A	N/A	Flare Traversable RT?	N/A	
				N/A	Landing Length (in)	N/A	N/A	DWS Provided?	N/A	
FOGGY MEADOW F	D	Surveyor Notes:		N/A	Landing Width (in)	N/A	N/A	DWS Contrast?	N/A	
the second second	All and	N/A		N/A	Landing Slope (%)	N/A	N/A	DWS Length (in)	N/A	
S States of S	100	1071		N/A	Landing X Slope (%)	N/A	N/A	DWS Full Width?	N/A	
	C POL	i de la companya de l		N/A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset (in)	N/A	
				N/A	Shared Landing?	N/A				
	- And and and	PROW/ADA:		N/A	Gutter Ponding?	N/A	N/A	Gutter Slope (%)	N/A	
	a start	Not Found, R304.2.2, R304.5.3		N/A	Gutter Lip Ht (in)	N/A	N/A	Gutter X Slope (%)	N/A	
	La la			N/A	Painted X Walk1?	No	N/A	Painted X Walk2?	N/A	
Company of the second s	1211				X Walk 1 Direction	To W		X Walk 2 Direction	N/A	
	A ALL ALL			N/A	X Walk 1 Width (in)	N/A	N/A	X Walk 2 Width (in)	N/A	
Street 1 Name LC	ONG FOREST DR	_			X Walk 1 Slope (%)	4.9		X Walk 2 Slope (%)	N/A	
Stop Condition-Street 2	StopSign				X Walk 1 X Slope (%)	3.8		X Walk 2 X Slope (%)	N/A	
Street 2 Name	N/A			N/A	Ramp inside XWalk1?	N/A	N/A	Ramp inside XWalk2?	N/A	
Stop Condition-Street 1	N/A				Road Slope (%)	N/A	N/A	Clear Space?	N/A	
					Road X Slope (%)	N/A	N/A	Clear Space to XWalk (in)	N/A	
				N/A	Any Obstructions?	N/A	N/A	Storm Grate/Utility Hazard?	N/A	
		Total Cost: \$	1850.00		Obstruction Type			Storm Grate/Utility Type		
						N/A			N/A	

Yes Surface Condition? (G/P)

